



Welcome to SAI Production Suite 22.0.4 SP4

The Flexi product group contains some of the world's most advanced tools for print production and sign making software. We have added many new features based on your feedback.

Operating Systems Supported

- Windows 11 (X64)
- Windows 10 32-bit (x86) or 64-bit (x64) processor
- Windows 8.1 32-bit (x86) or 64-bit (x64) processor

Installing on a Mac using parallels or bootcamp is not recommended and not supported.

SAi Production Suite 22.0.4

Build 4253

8 November 2023

New Features:

- Send to Epson Edge Print
- Censi Marks added to Label and Marks
- Summa color swatch added to swatches library
- Oracal 951 Swatch added to Oracal library
- Summa Material Library added to GoProduce driver

Improvements:

- After the subscription license is updated, the install manager will run in the silent mode not to interrupt open application.
- License Manager to show expiration date for expired license and link to manage subscription



- Added a index in the device tab to split the devices when there are multiple setups with same manufacturer/model using File or Folder port

New Printer Drivers:

- HP: L630, L630W
- Canon: M-series, Colorado 1630, Colorado 1640, Colorado 1650,
- Roland: LG-640/540/300, UG-642, AP-640, BN2
- LogoJet: UVx40R-SE, UVx40R PLUS, UVx40R PLUS SE, UVx40R PLUS DC SE, UVx90R, UVx90R SE, UVx90i, FSR90

New Cuter Drivers:

- Colex : Sharpcut Pro
- Summa: D Series S3, T Series S3

Drivers Improvement:

- Mismatch between Kongsberg circles marks and the job orientation
- Barcode for Kongsberg is printed on all 4 sides although only the left side is selected
- When disabling Barcode option for Kongsberg marks the RIP generate an error
- Incorrect color mode sent to Teckwin Teck_Twinner2513 SG Driver
- Zund registration marks not applied correctly. Issue reported on Flexi 3M version.
- Catch Exception error when sending job to HP Z series printer
- Incorrect resolution for Mutoh PJ2508 UF
- Mutoh VJ 1638x stretches prints
- Fixed random cut lines, Foison E24L driver
- Roland GX 500 media length locked at 984 inches
- Improved Multi-Layer printing on Mimaki UCJV300
- Mimaki UCJV300-160 CMYKLcLmW - not printing Varnish



- Mimaki CG-160 FXIIPlus cutter can't find cut job using ID Cut
- Mimaki JV 300-160 machine temperatures are showing up as Fahrenheit instead of Celsius

Bug Fixes:

- HP Latex does not post print job info to the cloud.
- Applying issue with preset that uses Alpha channel for white
- Fix a bug that RIP counter is not decreased when there is a RIP error
- Improvement for job queue updating when adding jobs
- Fix a bug where printing does not start if a nesting job is sent after being RIPPed first separately
- Fix a bug where printing would start before RIPPING after changing resolution in job that was sent.
- PM job queue speed improvement: Not to reconstruct the job queues each time a job is done
- Fix a crash opening angled screen dialog
- PM job queue speed improvement: Cache queue preview BMPs
- Fix writing of color names to named color ICCs in the Unicode version
- Not able to measure single color in Flexi Designer.
- Laser Cutter marks not changing values correctly when pressing up/down arrow.
- PDF Files not Deleted from Hot Folder
- Progressive JPEG files RIP error when applying finishing tools
- Printing while ripping doesn't work with large rotated nest job
- Large files having rip error, calculate memory allowance for JAWS instances based on the available memory and number of instances
- Nested jobs are rotating the Cut file in Flexi 21 and 22
- Incorrect number of copies shown when nesting single and multi-page documents
- Manually Weed Border causing an issue with Split Lines.
- White not printing correctly under SummaFlex mark.
- Printing via driver bridge is not working.



- Install Manager 32-bit error message when updating license with License Manager 32bit.
- Jobs stuck in Ripping Done mode for HP Latex
- Choke and Spread values do not change for Xenon printer.
- The curve display issue has been fixed for VD Profiling.
- Jobs with SummaFlex marks getting Rip Error in Flex 3M build 3727.
- Unable to change shade percentage for spot color object in Designer.
- Spot colors are missing after applying ICC profile with spot channels linearization.
- Choke under white not applied correctly when printing multi-copy. Reported in STS ink version.
- UI issue on the transparency tab in job properties of production manager with Chinese version.
- Select within tool not showing object attribute.
- Page number can be set higher than page range set by the user
- Inspire files not importing onto Flexi Designer 32-bit
- PM crashing when sending job to Epson SC-7000
- PM not responding after deleting cutter with barcode server and with TCP/IP port
- Contour cut preview not showing in transparency tab when positive offset is used
- Preview of JIG layout is not working properly with Chinese version
- Greek fonts displayed incorrectly with Greek characters
- Files imported Directly to PM with Cut are unable to read marks - Mutoh VC 1300
- Open contours in a group will prevent true shape nesting
- Vertical offset from DJP not respected by Summa S1 D140 for nested jobs
- After resetting Separations, spots are not displayed anymore
- Nesting jobs with and without CutContour line
- Transparent PNG creating lines when printing using File/Print
- RIP error when adding certain pdf documents in PM
- Wrong Data Format sending to Epson SC-F2000



- Contour Cut path and Outline lost when copied in Flexi
- Unicode kerning issue with special characters
- RGB color value incorrect for svg file imported into Flexi
- Tab Delimited.txt with Norwegian Characters does not import correctly with Auto Serialize feature
- Adobe Illustrator file locked after editing and Saving from Flexi
- Korean typing issue in FlexiSIGN 21 as well as in v22
- Not printing barcodes Summa F18 plotter with nested prints



Welcome to SAI Production Suite 22.0.3

The Flexi product group contains some of the world's most advanced tools for print production and sign making software. We have added many new features based on your feedback.

Operating Systems Supported

- Windows 11 (X64)
- Windows 10 32-bit (x86) or 64-bit (x64) processor
- Windows 8.1 32-bit (x86) or 64-bit (x64) processor

Installing on a Mac using parallels or bootcamp is not recommended and not supported.

SAi Production Suite 22.0.3

Build 4084

19 April 2023

Improvements

- Add a warning when incorrect value is typed for the object dimension in Design Central
- Support GCC 4-Point Positioning marks in GCC Jaguar drivers
- Hide upper right "Close" button from Color Profiler
- Amjobview added to Flexi installation.
- Option to allow vertical line on the left side of the print when using Kala marks
- Set Graphtec default cutter options to NONE, this will match GSP and use defaults from cutter
- Importing PM preferences after install Unchecked by default.



- Updated the PANTONE MATCHING SYSTEM® Solid Coated and Uncoated Libraries to include 224 new color identities and 5 new base colors

Bug Fixes

- When using SAI Automatic Mark 3 the intermediate registration marks get clipped
- No preview when opening a certain job in the loading state
- PM would close while ripping files and adding pdf at the same time
- Euro symbol (€) get replaced when opening a v22 file in v21
- FlexiDTF STS Edition 22 - Nested files cutting order issue
- Copies are missing from nested job preview after resizing one of the copies
- Printing incomplete Custom Spot Color Mapping list
- When using custom spot color for contour cut the color changes
- PRT file preview not showing in the printer controller software
- For certain devices the user cannot go back when adding a setup
- Error Messages after adding Epson SC-T7700D driver in PM
- Resetting the position of nested jobs with manual nesting after reopening JP
- CutContour is not completed when using Transparency tab to create it
- When installing driver for v22 folder for v21 would be created
- Nested CC jobs cut offset on Summa S1 D140
- "Add setup failed" when adding Mimaki TCP-1000 device
- Gradient sent from Flexi not previewing correctly in PM
- Send cut path from the job option from Default Job Properties not applied to a new job
- ICC profiles specified in job ticket file is not applied to a job
- Adding spacing between artwork and a barcode makes Summa look for marks in the wrong spot
- ContourCut Job with barcode and opos marks from Designer cuts on wrong side.



- Summa D140 R XY Line will not print
- When selecting White Type 'Under Color', white removed under the black until switched to transparency tab
- Memory leak when importing vectors with embedded ICC profiles
- Improving speed when importing file with gradients created of Lab colors
- Object would overlap after nesting in Designer
- When creating layered job, "child" job preview not visible
- Horizontal tiling preview not in correct order
- Cannon imagePROGRAF TM-300 removed 1200 resolution from media that does not support it
- Create transparent background incorrectly applied to PNG/TIFF data
- A line is added to the printing when Contrast is boosted in Color Adjustment Tab
- Design Central Color trace small color icons
- Perpetual Flexi would freeze when connected to network without internet connection
- Braille from Flexi 22 shifts position when opened in Flexi 21 and 19
- Incorrect label position after using Break Apart for multi-page document
- Color Management doesn't apply different ICC profiles to front and back image when using Sandwich mode
- Improved Speed when creating transparent background for "complex" images
- RIP process would freeze if trying to show separation preview for another job
- Cloud Window still looking for connection on offline installation
- Decimal separator issue on Norwegian locale
- The user can not reopen the JP after setting the Jig size to be bigger than the media size
- Fotoba mark is partially printed when is used with Step and Repeat and Labels



- The preview is not updating when changing ignore overprint options in the "Preview output channels" tab
- PDF Gradient issue importing into 21 or 22 (InDesign compatibility issue)
- When sending a cut job from Flexi to GX-640 alignment from left bottom corner changes to right
- PU command wrong in .PLT using Aristo driver
- Poll size not working for Mutoh VJ-1324X over TCP/IP
- Roland GS-24 scans only 3 out of 4 marks
- Fix handling of CMYK TIFF with unassociated alpha channel.
- Bullet Points don't work in flexi 22
- Issue importing PDF X4 files
- ColorBox it is not generating the tiff file
- Wrong Data Format when sending "repeat job" on Mimaki UCJV300-107
- Epson P700 communication issue
- Some text from old version of Flexi (v12) not render on File /Open
- Mimaki CG-160 FXII Plus cutter can't find cut job using ID Cut
- Print mode Error 206 on printer panel when sending to Mimaki JV-300 PLUS
- Maki issue importing PDF files from Windows 11 Scan App
- Transparency issue with for PDF X1A version 4 and 5
- Gradient preview in Production Manager
- Graphtec FC9000-160 (error E05015) when sending nested print/cut job with barcode
- hpldrjgl.dll Production Manager crash when sending jobs to HP and another printer manufacturer
- Line being added when using contrast is busted in Color Adjustment tab
- Difference in how profile is applied to Spot Color Mapping between v21 and v22
- Duplicated Graphtec BC ID's when starting datalink server
- Edit Template Border showing Chinese characters



- Error message using Scandinavian Characters in data file for Auto Serialization
- Error Messages after adding Epson SC-T7700D Setup
- Error loading or saving preset when the locale has comma as decimal point symbol.
- RIP Error on PDF with ICC profile on EPSON SC-T3170
- Mimaki ID Cut barcode not visible when creating Cut Contour Marks in Flexi
- Issue with pattern in PDF file when 30,000 pixel square was used as tiling pattern
- PM would freeze while adding PDF file when printing at the same time
- Registration mark embedded into job Mutoh VJ-1624x and Mutoh VC-1300
- Registration marks in R&P window don't match Production Manager
- RIP error while using DIP Tech driver
- The user can not decrease Cut along page border margins
- The user can not reopen the JP after setting the Jig size grater than the media size
- Tiles not printed in correct order and not matching in the overlap
- Braille position when exporting as older Flexi file format
- Tiling order preview incorrect
- Mismatch between display values and Lab values for Pantone color used in contour path
- When using SAI Automatic Mark 3 the intermediate registration marks get clipped
- Windows 11 Scan App pdf does not import
- Wrong Data Format when sending "repeat job" on Mimaki UCJV300-107
- Sending Variable Data Objects: Overlapping Objects in front not visible in PM



Welcome to SAI Production Suite 22.0.2

The Flexi product group contains some of the world's most advanced tools for print production and sign making software. We have added many new features based on your feedback.

Operating Systems Supported

- Windows 11 (X64)
- Windows 10 32-bit (x86) or 64-bit (x64) processor
- Windows 8.1 32-bit (x86) or 64-bit (x64) processor

Installing on a Mac using parallels or bootcamp is not recommended and not supported.

SAi Production Suite 22.0.2

Build 3852

10 November 2022



New Features

- Ability to remove white under the black color when printing white under and to adjust white density under the black color
- Print barcode IDs with Summa barcodes
- Option to change distance between Kala trimmers blades in the Marks section
- Option to duplicate jobs in the Production Manage queue

Improvements

- Added popup message when SAI Connect button is clicked in Flexi if SAI Connect is not installed
- Label option is now unchecked and disabled when a cutter mark is selected (cannot print labels with cutter registration marks)

Changes

- Grace period changes from 7 to 3 days for expired subscription license
- Removed Send to Virtual Sign from Flexi 22.0.2. Sent to VS is no longer supported

Bug Fixes

- Addressed chart size issue for X-Rite i1 Pro3
- Installing driver files for Epson SC-P906 from cloud
- Catch Exception error when printing to Epson SC906
- Mutoh VC-1800 not lifting blade between cuts
- Missing VLCD print control form driver options in GCC JF-240UF
- Addressed print quality issue with Epson SC-V7000 driver
- CMYK gradient from illustrator coming in as solid color
- Adding barcode to print only job
- Error in Color Profile Adjustment when entering RGB values
- Not able to add plt files to cutter job queues
- SVG imports in Flexi with two layers instead of one



- Issue with font styles for Adobe fonts
- Incorrect Roman character orientation for vertical text
- Improved RIP speed performance when mapping spot color as spot but ripping as process
- Installer freezes while installing Bonjour
- Preview and output not matching when label width not matching OPOS marks
- Missing elements when ripping pdf file
- Canon GP poll size not working
- Typing in "TAB" space stretching character to TAB space width
- Incorrect file date after saving
- When changing width of the label, job changes position as well
- Seiko M64-S driver options not sending correctly from RIP and Print dialog (such as uni or bidirectional print)
- Loading of Cut & Plot options from Flexi 8.5 files
- Roland GR2 Crop Marks not printing
- Applying margin to Cut Along Page Border for nested images
- PM Crashes adding Photoshop TIFF files
- Measuring colors in Color Mapping not changing CMYK values
- Printing ripped RTL file produces RTL error
- PDF containing DeviceN images imports incorrectly
- Issues adding Azon Matrix series 2 UV and UV Pro drivers to Production Manager
- Not printing to Mimaki TS100-160
- Error saving prt files on Roland IU when port is set to "folder"
- Moving cut job from one cutter queue to another will not keep number of copies
- Missing cut mark for Roland VersaCAMM VP 540i in Flexi Designer
- HP barcode printed on both top and bottom even though only one is selected
- Braille position shifting when older versions of files with braille opened in Flexi 22
- Font not exporting correctly to Adobe Illustrator file



- Additional tools flyout open in wrong position
- Greek characters not showing correctly
- Importing PDF file and choosing Link option creates an error
- Incorrect image size after importing into Designer
- Importing multipage pdf places pages one on top of another
- Registration marks not aligned when splitting job in layers
- Rational Angled Screen dither type generated only 1-bit output
- Handling font weight attributes while importing svg file
- Certain EPS and PDF files do not open correctly when imported. Objects are shifted.
- Fix typing of Arabic text
- Summa cutting only first set/panel of OPOS marks
- Inverted Variable Under with Choke for white prints extra lines
- Flexi would generate the same barcode IDs for Graphtec if different cut paths were sent from the same document
- Nesting hybrid jobs does not create cut layers/file
- Scandinavian characters not displayed correctly when Auto Serialization is used
- Job is rendered with overprint even when the overprint attribute is not set
- Menus incorrect when custom shortcuts are created for French version of Flexi
- Inconsistent job layouts with Mutoh 2 cut marks
- Fixed problem with Flexi not finding remote Production Manager on the network
- Adjusting layer attributes causing Flexi to crash
- Jig template printing cropped left and bottom when media margin is used
- When adding jobs to PM and "copy to job folder" option is checked, empty folders are created at the original location
- Tile panel margin incorrect when trying to reset to 0



Welcome to SAI Production Suite 22.0.1

The Flexi product group contains some of the world's most advanced tools for print production and sign making software. We have added many new features based on your feedback.

Operating Systems Supported

- Windows 11 (X64)
- Windows 10 32-bit (x86) or 64-bit (x64) processor
- Windows 8.1 32-bit (x86) or 64-bit (x64) processor

Installing on a Mac using parallels or bootcamp is not recommended and not supported.

SAi Production Suite 22.0.1

Build 3782

03 August 2022

Bug Fixes

- Poll size is not working on Mimaki SIJ-320UV.
- Barbieri LFP device is not scanning with Flexi 22.0.
- Auto-serialize feature causes a crash.
- System error message with mfc140u.dll when installing Flexi 22.
- Production Manager is not previewing grayscale image properly.
- Driver options are missing when sending cut job via network to Production Manager.
- CAS Fonts folder is not created under SAI Production Suite installation
- Corrected language issue with license manager.
- Poll size error Epson R5000 and S80600L.
- Horizontal mouse wheel scrolling is not working.
- Profile selections are missing when layered job are sent from RIP & Print dialog to HP 700W/800W.
- Incomplete Zund marks are printed (driver: Zund G3 L-2500)



- Jobs with 3 layers are not centered for HP 800W.
- Changes to Method, Unit Type, Category, or Material are not saved in Default Job Properties dialog.
- Memory leak when setting dimension or spacing to "0" for "Remove data in texture patterns".
- SVG files import incorrectly in v22.
- Issues with displaying symbols in the Insert Symbols dialog.
- Wrong barcode information is displayed in Job Info window for Graphtec FC9000
- Contour cut file is not generated when the print & cut file name contains Danish symbols.
- When adding Graphtec fc 4100-75 to Production Manager 22 freezes on "Processing Please Wait".
- Can't add setup for some Epson Stylus Pro models.
- Large transparent PNG files have issues applying contour effect.
- Media width is not maintained after relaunching Production Manager.
- Cut jobs with ZCC marks have offsets when combining nesting and "cut along page border".
- Color Vectorize tool is not working.
- Blinking icons in effect toolbar.
- When sending Ink Limit test, the program crashes.
- Measurement tool is not snapping to guideline.
- Color adjustment on white not applied to all rows with choking.
- RIP error with white/varnish only colormodes for Mutoh XPJ driver.
- OCC preview not showing correct colors.
- Erasing patterns doesn't work when applying to white only.
- Navigate the Auto-Serialize dialog by tab.
- Improve thumbnail images for job queues.
- No 'Step & Repeat' preview for diagonal and circular distributions.
- The chroma adjustment option is saved correctly in ICC profiles.

SAi Production Suite 22.0

Build 3760

22 June 2022



New Features

- Unicode
- Driver separated from the core application
- Transparency Tab
 - Create transparent background
 - Create Contour Cut using transparent background in Production Manager
 - Remove data in texture patterns
 - Use alpha channel to generate white data
 - Use transparency mask to generate white data
 - Slider for white density
- Create two separate names for CC path created with Cut Along the Border tool and when using transparency tab in the Production Manager
- Order Reprints
- Cut tab automatically added when contour cut is detected in the Production Manager
- Choke "only" white under color RIP generated data
- Added option to preferences to select launch 32-bit version of Production Manager
- Reorder of Setups in Production Manager
- Add output profiles button next to Output Profile dropdown
- Cut Page Crossing and Cut Strip Crossing added to Production Manager
- Ink Cost Estimation added to Job Estimation in Production Manager
- Thumbnails for jobs in Production Manager queue
- Ability to add job to already nested group
- Tile count in the job info pane
- Warning for very small tile
- Ability to choose the position for Labels
- One set of labels for nested or tiled jobs
- Ability to print labels with Fotoba marks
- Option to add space between HP barcode and the design



- ICut marks added to 64-bit Designer
- Add Filled Circles Options to SAI Automatic Segment Marks
- Kongsberg and Esko cutting tables support
- Ability to save JIG layout as eps file
- Dynamic marquee for Make Transparent in Designer
- Canon Swatch library
- Grafityp Swatch library
- Flexi Designer to communicate with OEM Production Manager of the same version
- After Receive "Rip Only" option for hot folder
- Ability to import preset into FlexiDESIGNER RIP&Print window
- Import Data from previous installation to open by default at the end of the installation
- Extra working message when deleting Job from Production manager
- Help Topics to point to new Zendesk help page

Bug Fixes from Flexi 21

- Translation issues on multi-layer job handling and split job by layers (German)
- Origin of text changes when converting to Braille
- Gap between the artwork and the bleed
- Output Channel Preview and Object Color Control are not showing Color Mapping
- Issues with Mimaki UCJV300-160 CMYKLcLmW driver
- Layered Job Reverses Layers
- Mimaki CG -160FX not detecting marks
- Issues adding HP desktop printer to PM as "desktop printer"
- Graphtec FC8600-130 default Registration Marks set to Segmented Area Type 1 (options issue)
- Import Text as Path not working on certain fonts
- Nesting file not printing with activated option "Send in Order they are added"



- Extra passes printer on HP L 700/800
- Catch exception in SendHeader()... error message when sending print jobs to a Epson SC-P20000
- Changing job positioning for HP L700/ 800 is ignored
- AmEpS80600.dll error
- Trying to use Open With option to open FS file with Hebrew name cause crash
- 232x98" at 100DPI .PSD documents don't populate when being loaded into PM, but 70DPI does
- Roland GX-24 USB Port not visible in port list
- HP Latex 570 Default Centering is moving vertical offset, not horizontal
- EPS/PDF imported directly to PM with cut line are unable to read marks - Mutoh VC 1300
- Color shift when using the option Device Linked ICC profile on the fly
- Wrong Channel order Truevis VG2-640
- Identical Summa/HP bar code ID's when a preset is applied that was saved from the job properties of a previous job
- Wrong Data Format error on Mimaki TS55-180
- Summa Flexi marks layout incorrect when rotating nested jobs in PM
- Preview issue of job properties when switching between the tabs
- Copying Chinese symbols in the designer's text tool show up as question marks
- Stop Marks always printed when selecting Kala XY marks
- Incorrect preview when the file contains embedded ICC profile
- Roland GR2 driver does not poll size
- Quality One Q Series 2448 Set up disappears after exiting PM
- Rip error when mapping colors with LAB values
- Cannot import PDF's created by scanning with HP scanner
- Crop Marks from Illustrator or InDesign drop from PDF when importing directly into PM



- Incorrect resolutions for Xenons i3200
- Driver Canon TM200 - Printing duplicated and distorted with resolution 1200x1200 Fine
- OPOS marks are not available for Summa S1 D60 D75
- Hybrid device not showing as cutters in OEM PM
- Converting RGB to CMYK results in an empty image if soft proof is enabled
- Issue with temp files if hot folder is on the network
- Graphtec cut job stacking vertically when number of copies changed in PM
- Color configured on the Separations tab is not saved in the Preset
- Changing CMYK channels to Spot in Separation tab does not work
- Issue exporting bitmapped images when in indexed color space
- Mimaki not cutting properly when using Intermediate Crop Marks
- QR code doesn't duplicate correctly if flipped 90 degrees
- Remove mask for EPS files imported into Flexi
- OCC profile does not keep fluorescent channel description
- Typo for Magenta in the Ink Settings
- Job properties with the cut path doesn't get updated when using adding job by Add Job->Open Job option
- RIP&PRINT: "Use PM settings" does not apply the correct ICC profile
- PNG file imports into Flexi with green background
- Files over 1.37m wide are rejected by the DGI FT-1608 software console
- Custom Color Mapping is not applied correctly when the job is sent from RIP and Print
- When customer sends print file by Send to VW and contour cut from Flexi cutter skips over 3rd cut mark
- Specific PS file imports incorrect size
- DGi PS-3206 doesn't print from Flexi 21
- Issues with Lab Colors in Flexi 21 after adding ICC profiles



New Printer Drivers

- 3D PRINTING: 3D PRINTING
- AC-COLOR: AC-COLOR UV2513
- ADDTOP: ADD-I3200-6C-B, ADD-I3200-4C-B, ADD-GEN5-4C-R
- ALLWIN: ALLWIN-KS-EP3200S-8C
- AM.CO.ZA: FastCOLOUR-F-3200-XP600-Dual
- Ao cheng: Ao cheng-PCA1080, Ao cheng-PCB1080, Ao cheng-PC4720
- Aojet: Aojet RY 2513SH, Aojet BY 3300KA_EX, Aojet RY 3300KR_EX, Aojet RY 2513KA_EX, Aojet RY 3300RA_EX, Aojet RY 5000V, Aojet RY 3300Versa, Aojet XHS 1800Versa UV
- ApexJet: ApexJet-EPS3200 Series
- Armyjet: Armyjet-Ricoh-UV, Armyjet-Ricoh-MINI UV, Armyjet-EPSON-UV, Armyjet-EPSON-MINI UV, Armyjet-EPDX57-SY, Armyjet-EPXP600-SY, Armyjet-Toshiba-MINI UV, Armyjet-Toshiba-UV, Armyjet-MINI TX V2, Armyjet-8C, Armyjet-MINI TX V3, Armyjet-4720-BYHX, Armyjet-DX5-BYHX
- AUMEX: AUMEX-t3200, AUMEX-x3200
- AUTOTRAN: ROCC-R5i, ROCF-RICOH, ROCB-RICOH, ROCB-KONICA
- Avanti: Avanti A160i Series, Avanti I-X, Avanti DTF, Avanti F1 Solvent, Avanti Ai Plus Series Veloce, Avanti AT-ix and Veloce Series
- AW: AW-BYHX-RICOH, AW-AK-GEN6
- Azon: Edge, Soniq, Pronto Plus, Pronto Plus Neon X 2
- Bass Bowei: Bass Bowei-UV-RICOH-G5I, Bass Bowei-MiniUV-RICOH-G5I
- BC PRINTER: ZT-HS-TX800, ZT-3200UV_Roll
- BEATUS: BENI 1165UV, BENI 6050UV, BENI 9060UV, BENI 1112UV
- Bergen: BI-H DX5 4C, BI-H 3200-3L, BI-H 3200-3L 150D, BI-DP 512-1024-14pl, BI-DP 512-1024-42pl, BI-DP 512i-30pl, BI-Q-JET Plus BI3200, BI-B DX5 4C, BI-B KM256-42pl, BI-B KM256-14pl, BI-B KM512-1024-42PL, BI-B KM512-1024-14PL, BI-DP XAAR1201, BI-DP SG1024-25PL-2C, BI-H S3200 TX, BI-B S3200 TX, BI-B 4720 TX
- BL-YWD: BL_i3200_UVPrenter, BL_DX7_UVPrenter, BL_DX10_UVPrenter, BL_G5i_UVPrenter
- Blueprint: Blueprint-Konica1024i-6pl, Blueprint-EP5-2-ECO-SY, Blueprint-Konica1024a-6pl
- BM: Michelangelo Genius III



- BOSSRON: WT-SY-DX5DX7, WT-SY-4720, WT-SY-4720-UV, WT-BYHX-DTF3200-UV
- BrGroup: GUV3212R4-1W
- BSKY: BSKY-MiniUV-RICOH-G5I
- CET Color: CET K2-250H, CET Q-250H, CET Q5/Q6-250H, CET XPRESS-250H, CET Q-500H, CET Q5/Q6-500H, CET K2-1000H, CET Q-1000H, CET K2-250, CET Q-250, CET Q5/Q6-250, CET XPRESS-250, CET K2-1000, CET Q-1000, CET Q5/Q6-1000, CET XPRESS-1000
- CoStraight: CoStraight BY 3300KA_EX, CoStraight RY 3300KR_EX, CoStraight RY 2513KA_EX, CoStraight RY 3300RA_EX, CoStraight RY 5000V, CoStraight RY 3300Versa, CoStraight XHS 1800Versa
- CrystalJet: CJ-KM1024A-BYHX, CJ-KM1024A-BYHX-DX, CJ-SYEPSON
- DACEN: DACEN-I3200, DACEN-I3200-MINI, DACEN-I1600, DACEN-I1600-MINI, DACEN-G5i, DACEN-G5i-MINI, DACEN-G6, DACEN-G6-MINI, DACEN-1024i, DACEN-1024i-MINI, DACEN-Toshiba, DACEN-Toshiba-MIN, DACEN-XP600, DACEN-XP600-MINI
- Delone: Delone-BY i3200UV, Delone-BY i3200ECO, Delone-BY i3200WA, Delone-BY G5I UV, Delone-BY G5I ECO, Delone-BY G5I WA, Delone-HS i3200UV, Delone-HS i3200ECO, Delone-HS i3200WA
- DGI: FT-3204X, VE-3204X, FT-1908, FD-1908
- Digital Printer: BF-4720-8C-HS-Mini, BF-HS-TX800-Mini, BF-DX6-A3, BF-UV-DTF-HS
- Dilli Precision: Neon Sun
- DING: DING-HX-I3200-UV, DING-HX-I3200, DING-BYHX-I3200-UV, DING-BYHX-I3200
- DMACI: DMAC6090 G5i
- Docan: Docan HS
- DTGTEX: DTGTEX-X5
- EDSON: EDS-X AAR
- Ejet: Ejet_SG_1024i_CS_BYHX, Ejet_EP_5113_BYHX_UV,, Ejet_HX_A3UV
Ejet_DTF70_BYHX, Ejet_DTF70_SY
- Epson: SC-P700, SC-P706, SC-P704, SC-P703, SC-P708, SC-PX1V, SC-P900, SC-P906, SC-P904, SC-P903, SC-P908, SC-PX1VL, SC-T3700E, SC-T3700D, SC-T3700DE, SC-T5700D, SC-T7700D, SC-T7700DL
- Eyecolor: Eyecolor-I3200-HS, Eyecolor-I3200-HS-UV, Eyecolor-I3200-BYHX, Eyecolor-1800U-i3200-UV



- F-PRINT: F-PRINT_CE4_Mini, F-PRINT_GN5_SHRY_UV_Mini, F-PRINT_HS_GN5_150_UV_Mini, F-PRINT_HS_GN5_180_UV_Mini, F-PRINT_HS_NET_EPS3200UV_V_Mini, F-PRINT_HS_NET_EPS3200UV_LM_Mini, F-PRINT_PC1080_HS_3S_Mini, F-PRINT_HS_GN6_180_UV_Mini, F-PRINT_HS_GN6_180_UV, F-PRINT_HS_I3200_LM, F-PRINT_HS_I3200_V, F-PRINT_HS_I3200UV_LM_Mini, F-PRINT_HS_I3200UV_V_Mini, F-PRINT_HS_I3200UV_LM, F-PRINT_HS_I3200UV_V, F-PRINT_DX5DX7_HS_Mini, F-PRINT_E603_9C
- FEDAR: FEDAR-FD5268E
- Fei Yeung Union: FY-SCN-2513R, FY-UV_I3200_HS
- Flora: Flora-S3200, Flora-EP, Flora-EP-H, Flora-3202P-R
- Fluid Color: Fluid Color R Series Gen5, Fluid Color R Series Gen6, Fluid Color Z Series 363, Fluid Color Z Series 605
- FLY-TOO: FLY-TOO-1802A-DX5, FLY-TOO-1802A-DX7, FLY-TOO-1802A-DX5113, FLY-TOO-1700G-DX5, FLY-TOO-1700G-DX7, FLY-TOO-1700G-DX5113, FLY-TOO-3300V-G5, FLY-TOO-1802F-DX5113, FLY-TOO-3308-512I, FLY-TOO-3304-512I, FLY-TOO-1325UV, FLY-TOO-330UR-1024I, FLY-TOO-330UR-1024I-WV, FLY-TOO-1325UV-3688, FLY-TOO-3300GF-G5, FLY-TOO-3300GF-G5-WV, FLY-TOO-5000UR-G5, FLY-TOO-JF-XP600-1H, FLY-TOO-JF-XP600-2H, FLY-TOO-JF-XP600-4H, FLY-TOO-XHS-6090UV-3H, FLY-TOO-XHS-2000D-UV, FLY-TOO-BYHX-4720, FLY-TOO-JF-4720, FLY-TOO-JF-DX5, FLY-TOO-XR1201-UV, FLY-TOO-XR1201-ECO, FLY-TOO-3300V-G5-DX, FLY-TOO-XHS-2000D-DX FLY-TOO-XR1201-DX, FLY-TOO-XHS-6090UV-3H-DX, FLY-TOO-5000UR-G5-DX, FLY-TOO-1325UV-DX, FLY-TOO-DX5-XHS, FLY-TOO-DX7-XHS, FLY-TOO-4720-XHS, FLY-TOO-XP600-XHS, FLY-TOO-BYHX-4720-UV, FLY-TOO-SY-XP600, FLY-TOO-SY-XP600-UV, FLY-TOO-SY-XP600-6090UV, FLY-TOO-BYHX-60HT, FLY-TOO-BYHX-S60TH, FLY-TOO-SY-DX5DX7, FLY-TOO-SY-4720, FLY-TOO-SY-4720-UV, FP-DX5, FP-DX5-Dual, FP-DX7-A, FP-DX7-A-Dual, FP-DX7-B, FP-DX7-B-Dual, FP-EP4720, FP-XP600
- Forni: Forni-SZ-4720-UV, Forni-i3200-BYHX, Forni-RICOH-JLH, Forni-i3200UV-RY, Forni-RICOH-Hoson, Forni-Konica-BYHX
- Fortune: YF-3200UV, YF-5200G6, YF-KM1024i-5200, YF-UV-I3200, YF-UV-I3200-WV, YF-2512-G6-BYHX, YF-1704-i3200, YF-1700XP, YF-N700
- GCC: GCC JF-2418UV
- Gethray: Gethray-HS-EPSON-I3200
- GongZheng: GongZheng GZW2513_T3200, GongZheng GZH6600, GongZheng GZT1612GI, GongZheng GZF1808D



- GuangCai: GuangCai-2513RY, GuangCai-9060RY, GuangCai-9060WLY
- GUANGCHEN: GC-9060UV, GC-R180UV, GC-HS-I3200-9060UV, GC-HS-G5I-9060UV
- GZBK: GZBK-UV-XP600, GZBK-3200U1-9060, GZBK-3200U1, GZBK-S2070-3, GZBK-A3-3452, GZBK-UV-2513
- HC: HC-Printer, HC-Printer-XZ
- HeXuan: HX-PS-60, HX-19EA-8PULS
- HF: HF-A302X-S, HF-A302A-S, HF-A102X-S, HF-A102A-S, HF-A104X-S, HF-A104A-S, HF-A302X-H, HF-A302A-H, HF-A102X-H, HF-A102A-H, HF-A104X-H, HF-A104A-H
- HKprinter: HKprinter-BXJ, HKprinter-UV-HN, HKprinter-UV-DN
- Honytek :Honytek-BYHX-I3200-8C, Honytek-SY-XP600-8C, Honytek-BYHX-I3200-PRESS, Honytek-XY-I3200-PRESS, Honytek-XY-I3200, Honytek-SY-XP600-302, Honytek-HX-XP600-302, Honytek-BYHX-I3200-180, Honytek-BYHX-I320-UV6090, Honytek-SY3200-302 9C, Honytek-BYHX-I3200-13,
- HS: HS i3200 UV
- HYL Printer: HYL1301-3200, HYL1301-DX5 HYL1301-DX5-UV HYL1301-I3200-CW, HYL-AF3200E1HS, HYL-1801-HS, HYL-1601-A3
- INKGIANT: BF-4720X-WV-Mini, BF-HS4720-WV-Mini, BF-4720-8C-HS-Mini, BF-HS-TX800-Mini, BF-DX6-A3, BF-UV-DTF-HS
- Inkjetprinter: Inkjetprinter-BJ-3200-UV, Inkjetprinter-BJ-3200-MINI, Inkjetprinter-BJ-3200-DX, Inkjetprinter-BJ-1440-DX, Inkjetprinter-HS-3200-UV, Inkjetprinter-HS-3200-MINI, Inkjetprinter-HS-3200-DX, Inkjetprinter-HS-1080-DX, Inkjetprinter-SY-3200-UV, Inkjetprinter-SY-3200-MINI, Inkjetprinter-SY-3200-DX, Inkjetprinter-SY-1440-DX, Inkjetprinter-SY-1080-UV, Inkjetprinter-SY-1080-MINI, Inkjetprinter-SY-1080-DX, Inkjetprinter-RY-Ricoh-UV
- J.S.Machine: J.S.Machine-SLIM, J.S.Machine-Xquis, J.S.Machine-Yarn
- JADE: JADE-KM-512i-14PL, JADE-KM-512i-6PL, JADE-GEN5-7PL-WV-4C, JADE-GEN5-7PL-WV-6C, JADE-Ricoh2220-3PL-WV-4C, JADE-Ricoh2220-3PL-WV-6C, JADE-KM-1024i-30PL, JADE-CE4UV, JADE-KM-1024i-6PL, JADE-EP4720, JADE-EPL1440-UV, JADE-EPL1440, JADE-EPSON-HS, JADE-EPSON-UV-HS, JADE-GEN6-UV, JADE-TF9060A-CE4, JADE-TF1016A-CE4, JADE-TF9060-GEN5, JADE-TF1016-GEN5, JADE-TF9060-GH2220, JADE-TF1016-GH2220, JADE-EP4720-UV, JADE-T2204G5i, JADE-T1800UV-GEN5, JADE-KM-1024i-13PL-UV, JADE-GEN5-7PL-MC-4C, JADE-TF9060-GEN5-HS JADE-TF9060-GEN6-HS, JADE-TF9060-EPSON-UV-HS,



JADE-TF9060-G5I-UV, JADE-TF1016-G5I-UV, JADE-GEN5-HS-UV, JADE-GEN6-UV-BYHX, JADE-TF1810-GEN5, JADE-TF2513-G5I-UV, JADE-I3200-BYHX-DTF

- JESI: JESI9060-XP600-UV, JESI9060-I3200-UV, JESI6090-XP600-UV, JESI6090-I3200-UV, JESIA3-XP600-TH, JESIA3-TX600-TH, JESIA3-I3200-TH
- JSW-XSJ: JSW KS3300-BYHX, JSW Ricoh3300-BYHX, JSW KS3300-BYHX JSW QR3200G, JSW F2513G, JSW 3200R-KM6988H, JSW EPS3200-F6090, JSW Konica-6pl-1600R, JSW EPS3200-F2513G, JSW F3220G, JSW KS3300-UMC, JSW KM3300-UMC, JSW XP600-JF, JSW SFast G5, JSW Ricoh3300-BYHX, JSW Ricoh3300-HS
- JULI
 - JLSY600PC1080
 - JLSY600EPS3200
 - JLHS600PC1080
 - JLHS600EPS3200
 - JLHS600EPS1600
- KaiMeiJie
 - KMJ-1902X-1602X
 - KMJ-1901X-1601X
 - KMJ-1901W-1601W
 - KMJ-1902W-1602W
 - KMJ-1901A-1601A
 - KMJ-1902A-1602A
 - KMJ-1901B-1601B
 - KMJ-1902B-1602B
- Kalers
 - Kalers-KM512-1024pl-B
 - Kalers-KM512i-30pl-B
 - Kalers-KM1024i-30pl-B
 - Kalers-W5113-HS
 - Kalers-DX5-HS
 - Kalers-I3200-HS
 - Kalers-I3200-B
 - Kalers-I3200-8C-HS
 - Kalers-GEN5-UV-UMC
 - Kalers-GEN6-UV-UMC
 - Kalers-GEN5-UV-B
 - Kalers-GEN6-UV-B



- Kalers-W5113-WV-HS
- Kalers-DX5-WV-HS
- Kalers-I3200-WV-HS
- Kalers-I3200-WV-B
- Kalers-DX5-B
- Kalers-DX5-WV-B
- Kalers-GEN5-UV-HS
- KEUNDO
- ALPHA 1600A
- SC-GT 1600A
- SC-A1600-WG
- SC-A1600-OG
- KEUNDO-KUF2513-S508
- KEUNDO-KUF2030-S508
- KEUNDO-KUF2513-S1020
- KEUNDO-KUF2030-S1020
- KEUNDO-KUF2513-R4
- KEUNDO-KUF2030-R4
- KEUNDO-SK508TX-4C
- KEUNDO-SK508TX-8C
- KEUNDO-Gen4-6C
- KEUNDO-Gen5-6C
- KEUNDO-Gen5-7C
- KEUNDO-SG1024-12PL
- KEUNDO-SG1024-30PL
- KEUNDO-6C-150
- KEUNDO-Gen5-1CH-UV
- KEUNDO-Gen5-2CH-UV
- KEUNDO-Gen5-UV3200
- KEUNDO-RICOH
- KEUNDO_Wrich_GEN5
- KEUNDO-M3200UV-J
- KEUNDO-Epson-600
- KEUNDO-Txsh-4C
- KEUNDO-Txsh-6C
- KEUNDO-Txsh-8C



- KG Print
 - KG Print-W
 - KG Print-O
 - KG Print-DX5DX7
 - KG Print-W5113
 - KG Print-XP600-2HD
 - KG Print-AT-DX5DX7
 - KG Print-AT-5113
 - KG Print-HS-4720
 - KG Print-XP600-1HD
- KINGJET
 - KJ302A-XP600
 - KJ302A-4720
 - KJ302B-XP600
 - KJ302X-I3200
 - KJ602-I3200
 - KJ602-4720
 - KJ604-I3200
 - KJ604-4720
 - KJ602BJ-4720
 - KJ6090UV-SY
 - KJ9060UV-G5i
- KIN WAH
 - KW-B-GEN5
- Kucai: KC-LT-DX5-SY-TX
- KuChi
 - KuChi-I3200
 - KuChi-I3200-W
 - KuChi-I3200-UV
 - KuChi-XP600-W
- Letop
 - LETOP-HS-G5
 - LETOP-HS-I3200-8C
 - LETOP-BYHX-3200-UV
 - LETOP-BYHX-3200-TX
 - LETOP-BYHX-i3200



- Liyu
 - LY_DSJ_RB_BYHX_4
 - LY_DSJ_RB_BYHX_6
 - LY_DSJ_KY_LED_4
 - LY_DSJ_KY_LED_6
 - LY_KCJ_RB_PCIE_4
 - LY_KCJ_RB_PCIE_6
 - LY_KCL_RB_PCIE_4
 - LY_KCL_RB_PCIE_6
 - LY_FS_NB_LED_4
 - LY_FS_NB_LED_6
 - LY_PCT_RA_BYHX
 - LY_PCT_RB_BYHX
 - LY_PZN_EC
 - LY_DS_RA_BYHX_4
 - LY_DS_RA_BYHX_6
 - LY_DS_RB_BYHX_4
 - LY_DS_RB_BYHX_6
 - LY_SP_4
 - LY_SP_6
 - LY_PZN_KY_LED
 - LY_DQ20_ED_BYHX
 - LY_DQ20_EC_BYHX
- Locor: Locor-1601
- LongKe
 - LongKe-I3200
 - LongKe-Ricoh-10C-MINI
 - LongKe-I3200-MINI
 - LongKe-RIOOH-5#-G5i-MINI
 - LongKe-RIOOH-5#-G5i
 - LongKe-one pass
 - LongKe-i3200-paper
 - LongKe-RICOH-G6-HS
 - LongKe-G6-6C-3#
 - LongKe-G6-6C-3#-MINI
 - LongKe-CY-XA2002



- M-COLOR
 - M-COLOR-HSDX6
 - M-COLOR-BYHXI32
- Macan
 - MACAN-M-1801-I3200
 - MACAN-M-1802-I3200
 - MACAN-M-1801-4720
 - MACAN-M-1802-4720
 - MACAN-M-1801-DX5
 - MACAN-M-1802-DX5
 - MACAN-M-1801-XP600
 - MACAN-M-1802-XP600
- MAGICJET
 - MAGICJET-RICOH-G5-BYHX
 - MAGICJET-RICOH-G6-BYHX
 - MAGICJET-KM1024i-SHE-BYHX
 - MAGICJET-KM1024i-MHE-BYHX
 - MAGICJET-KM1024A-SHE-BYHX
 - MAGICJET-EPSON-i3200-BYHX
 - MAGICJET-KYOCERA-KJ4B-BYHX
- Megajet
 - MEGA-SUB-6-8H
 - MEGA-DX5-HS
 - MEGA-EP3200-HS-ECO
 - MEGA-EPXP600-SY-WV4C-PIGMENT
 - MEGA-EPXP600-SY-WV6C-PIGMENT
 - MEGA-EP3200-SY-8C
 - MEGA-EPXP600-HS-WV
 - MEGA-EP3200-HS-8C
 - MEGA-EP4720-BYHX-WV-PIGMENT
 - MEGA-EP4720-HS-WV-F
 - MEGA-2513FlatbedUV
 - MEGA-I3200-BYHX-WV
 - MEGA-EPTX800-HS-WV
 - MEGA-DX6-6C-2-ECO



- Mehta: RasterJet: RS-RJ-1016 CE4-KN, RS-REC-1800EPX i3200
- MeiTu
 - MeiTu-DPI3200Plus
 - MeiTu-DPI1800Plus
 - MeiTu-DTF-40
 - MeiTu-DTF-60
 - MeiTu-DTF-40plus
 - MeiTu-DTF-60plus
- Meson
 - Meson CMYKWVP
- MGDTF
 - MGDTF-EP4720-HS-WV-PIGMENT
 - MGDTF-EPXP600-SY-WV4C-PIGMENT
 - MGDTF-EPXP600-SY-WV6C-PIGMENT
 - MGDTF-EPXP600-HS-WV
- Mimaki
 - TS330
 - CJV330-130
 - CJV330-160
 - JV330-130
 - JV330-160
 - JFX600
 - UJF-7151 Plus
 - JFX550
- MiniUVPrinter
 - MiniUV-F1080
 - MiniUV-I3200
 - MiniUV-G5I
- Monotech
 - Pixel Jet Konica BYHX
 - Pixel Jet UV F9060
 - Pixel Jet Toshiba F2512
 - Pixel Jet HB2000-KM1024i
- MPADigital
 - MPAD-Flatbed G5i-HS
 - MPAD-Flatbed Toshiba-YL



- MPAD-Hybrid-KM1024a-BYHX
- MPAD-Flatbed-KM1024a-BYHX
- MPAD-G5G6-Royal
- MPAD-G5G6-HS
- MPAD-G5G6-BYHX
- MPAD-I3200-BYHX
- MuchColours
 - MuchColours-K36
 - MuchColours-Mig100
 - MuchColours-K36H
 - MuchColours-K86
 - MuchColours-Mig50
 - MuchColours-Mig360
- Mutoh
 - XPJ-1642WR
 - VJ-1628MH (KCMY/KCMYWW)
 - VJ-1628MH (KCMYLcLmLk/KCMYLcLmLkW)
 - VJ-628MP (KCMYLcLmLkW)
 - XPJ-1341SR-P
 - XPJ-1641SR-P
 - VJ-1638UH2
 - VJ-1638UR2
- MyJet
 - MyJet-G6-HS
 - MyJet-SY_i3200_WCV
- MYPRINTER
 - MP-I3200ECO
 - MP-702T
 - MP-704T
- NEW HIGH COLOR
 - XSC-700D-SY
 - XSC-700D-HS
 - XSC-SUB
- Novi
 - Novi-FZ-DTF60
 - Novi-UV0609-CE4M-H



- Novi-FZ-DTG
- Novi-FZ-DTG-II
- Novi-FZ-DTF37-1600
- Novi-FZ-DTF37-4720
- OMAGICJET
 - Omajic-2513
 - Omajic-UV-XP600
 - Omajic-HS_2513_3200
 - Omajic-HS_G5I
 - Omajic-HS_G5
 - Omajic-HS_G6
 - Omajic-DTF_XP600
- Online Digital
 - oneline-MINI TX V3
 - oneline-4720-BYHX
- Optimum Digital Planet
 - Maxima INNOs
 - Maxima INNOs UV
 - Plasma
 - Picasso L
 - Maxima GT2
 - KR
 - KJ
- Oric
 - Oric 3200_Ricoh_RY
- PO-TRY
 - POTRY-I3200-AT600
 - POTRY-I3200-AT1900
 - POTRY-I3200-HX600
 - POTRY-I3200-SY300
 - POTRY-XP600-SY300
- POLYTECH
 - POLYTECH-8C
- PrintDot
 - PD-RV1809
 - PD-03-8_1024I_BYHX



- PD-03-8_1024I_UMC
- PD-03-8_512I_BYHX
- PD-03-8_512I_UMC
- PD-F1
- PD-18-i3200
- PD-1802E
- PD-1802X
- PS
- PS-3325
- PS-PDCM
- PS-3320T
- PSI
- ROCC-R5i
- ROCF-RICOH
- ROCB-RICOH
- ROCB-KONICA
- Rikang
- Rikang-UV6090X
- Rikang-YSY-926X-H
- Omajic-HS-3200
- Rikang-HS-I3200-8C
- RIPControl
- PRINTTYPE-TC Series
- PRINTTYPE-FD Series
- ROCJECTS
- ROCC-R5i
- ROCF-RICOH
- ROCB-RICOH
- ROCB-KONICA
- Roland
- TrueVIS VG3-300
- TrueVIS VG3-640
- TrueVIS VG3-540
- TrueVIS SG3-300
- VersaStudio BN-20A
- VersaUV LEC2-330 CMYKOrRWhWh



- VersaUV LEC2-640 CMYKOrRWhWh
- VersaUV LEC2-330 CMYKRePrGIW
- VersaUV LEC2-640 CMYKRePrGIW
- Royal
 - Royal-SJZ-2513UV
- SaiTu
 - SaiTu-JD-KM512i
 - SaiTu-RY-Gen6
- SAMPRINT
 - SAMPRINT SRF-1808
 - SAMPRINT SR for oval
 - SAMPRINT SEO-series-F
- SENDOA
 - SENDOA-STX1632EPS
 - SENDOA-HTX1632EPS
 - SENDOA-TX2PET
- Shanghu
 - SH-177
 - SH-600
- SID Signs
 - SID Triton I Series
- SiniColor
 - SinoColor SC-GEN6
 - SinoColor ProJet_MiniTX
- SinoPRINT
 - SP-347S
- Skycolor
 - SKYCOLOR-EPS3200-8H
 - STORMJET-EPS3200-8H
 - SKYCOLOR-EPS3200-8C
- SLJET
 - SLJET-GEN6
 - SLJET-G5I
- SMJET
 - SMTJET-BYHX-KM512I-30PL
 - SMTJET-HS-I3200-8C



- ORIC
 - Oric R-Gen4
 - Oric R-Gen5
 - Oric RUV-Gen4
 - Oric RUV-Gen5
 - Oric O2715-Gen5
 - Oric E-4C
 - Oric E-6C
 - Oric E-8C
 - Oric GH2200
 - Oric DX5-2WV
 - Oric DX5-B
 - Oric BE-1800
 - Oric WH-R-Gen5
 - Oric OS6045
 - Oric 3200_Ricoh_RY
- Sprinter
 - Sprinter-DDP-A1E-I3200
 - Sprinter-BYHX-KM1024I-6PL-8C
- SSX
 - SSX-Royal-G5G6
 - SSX-Royal-GH2220
 - SSX-HX
 - SSX-BYHX
 - SSX-One pass
 - SSX-SY-XP600
 - SSX-Royal-One pass
- SUBLISTAR
 - SUBLISTAR-UV-STAR III
- Sunthinks
 - Sunthinks-Royal-G5G6
 - Sunthinks-Royal-GH2220
 - Sunthinks-HX
 - Sunthinks-BYHX
 - Sunthinks-One pass
 - Sunthinks-SY-XP600



- Sunthinks-Royal-One pass
- SUNUSER
 - SUNUSER-BG-2513
 - SUNUSER-BK-2513
- Sunwin
 - W-JET-G5i-UV
 - W-JET-I3200-UV
- Surwi
 - Surwi-S700-HX
 - Surwi-S700-AT
 - Surwi-S300-HX
 - Surwi-S300-AT
 - Surwi-S2000-HX
 - Surwi-S2000-AT
- Taimes
 - Taimes-TF9060-GEN5-HS
 - Taimes-TF9060-GEN6-HS
 - Taimes-TF9060-EPSON-UV-HS
 - Taimes-TF9060-G5I-UV
 - Taimes-TF1016-G5I-UV
 - Taimes-GEN5-HS-UV
 - Taimes-GEN6-UV-BYHX
 - Taimes-TF1810-GEN5
 - Taimes-TF2513-G5I-UV
 - Taimes-I3200-BYHX-DTF
 - Taimes-XP600-SY-DTF
 - Taimes-TF1810-G5I-UV
 - Taimes-G5I-UV
 - Taimes-I3200-SY
- TD Printer
 - TD-UV3050-1H
 - TD-UV6090-3H
 - TD-UV6090-I3200
 - TD-TX3050-DTF
 - TD-DTF
- Techjet



- Techjet BY 3300KA_EX
- Techjet RY 3300KR_EX
- Techjet RY 2513KA_EX
- Techjet RY 3300RA_EX
- Techjet RY 5000V
- Techjet RY 3300Versa
- Techjet XHS 1800Versa UV
- Tekwin
 - Teck-LP-C10
- Textalk
 - Textalk JG1808
- ThunderJet
 - ThunderJet AQ_I3200
 - ThunderJet GS_A
- Titan
 - TT-4720-8C-HS
 - TT-4720-8C-HS-Mini
 - TT-4720-LK-HS-Mini
 - TT-I3200-10C-HS
 - TT-UV DTF-HS
 - TT-4720-4C-HS
 - TT-DX6-A3
 - TT-SY-XP600-A3
 - TT-1080
 - TT-1080UV
 - TT-1080UVmini
 - TT-HS-TX800-Mini
 - TT-HS-XP600-Mini
- TK Printer
 - TK-DTF
- TRUE-DPI
 - TRUE-DPI-F9060
 - TRUE-DPI-F2513
 - TRUE-DPI-F3220
 - TRUE-DPI-F1016
- TUHUI



- TH-6090UV-XHS-XP600
- TH-6090UV-JF-CE4M
- TH-9060UV-JF-CE4M
- TH-7590UV-JF-CE4M
- TH-6090UV-SY-XP600
- TH-6090UV-BYHX-I3200
- TH-2000UV-HS-I3200
- TH-3200UV-HS-I3200
- TH-2000UV-HS-DX5
- TH-3200UV-HS-DX5
- TH-2000D-HS-XP600
- TH-2000D-SY-XP600
- TH-AH480
- TH-A520
- TH-602-BYHX-I3200
- TH-602UV-BYHX-I3200
- TH-602CM-SY-XP600
- WAN LI DA
- WLD-RICOH
- WLD-EPS
- Weilai
- Weilai-3200
- Weilai-G6
- Wit-Color Digital
- ULTRA9100-EP3200 UV
- ULTRA BYHX-KJ
- WST
- WST-EPS-HS
- WST-UVPrinter
- Xenons
- Xenons-I3200-12C
- Xenons-CD1800K
- Xenons RICOH-WV-B
- Xenons-CD1800R
- Xenons-I3200-DTF
- Xenons-S3200



- XSJ TX
 - XSJ-FD70
 - XSJ-FD70-1H8C
- Xuli
 - XL-3204i-UV
 - XL-X6-2600
 - XL-X6-2613
- Y-PRINTER
 - YP-SY-I3200
- YAGENGFU
 - YGF-TOP2000-D
 - YGF-TOP2000-H
 - YGF-6080UV-I3200
 - YGF-6080UV-XP600
 - YGF-6080UV-DX5-8C
- YASELAN
 - YSL-DPCS_G5I_600DPI
 - YSL-B_I3200A1_CS
 - YSL-D_G5iCL
 - YSL-B_I3200
 - YSL-DPCS_G5I_600DPI_DX
- YINCHENG
 - YINCHENG-2513
 - YINCHENG-3020
 - YINCHENG-EP2513
 - YINCHENG-EP3020
 - YINCHENG-G5I
 - YINCHENG-GH2220
 - YINCHENG-GEN6
 - YINCHENG-I3200
 - YINCHENG-XAAR
 - YINCHENG-DX5DX7
 - YINCHENG-4720
 - YINCHENG-DX57-SY-8C
- YinDu
 - YinDu-BJ-3200



- YinDu-HS-3200
- YinDu-SY-3200
- Yingcai
 - YC3321-GEN6-1H2C
 - YC3313-I3200-1H4C
 - YC2513-GEN5-1H2C-RY
 - YC1610-GH2220-RY
 - YC1610-XP600-WLY
 - YC1610-TX800-WLY
 - YC1610-DX5/7-HS
 - YC1610-GEN5-HS
 - YC1610-GEN5-RY
- Yinhan
 - YH-RM-N-J
 - YH-RM-N-B
 - YH-RM-N-H
- YITE
 - YITE-512I
- YSU
 - YSU-K8-S-35PL
 - YSU-K8-C-35PL
 - YSU-K8-S-14PL
 - YSU-K8-C-14PL
 - YSU-K8-S-42PL
 - YSU-K8-C-42PL
 - YSU-128-C
 - YSU-K8-S-35PL 6C
 - YSU-K8-C-35PL 6C
 - YSU-K8-S-14PL 6C
 - YSU-K8-C-14PL 6C
 - YSU-K8-S-42PL 6C
 - YSU-K8-C-42PL 6C
 - YSU-128-C 6C
 - YSU-S1
 - YSU-K512-D4C
 - YSU-KS1



- YSU-S1-8C
- YSU-KM1024-14pl-W
- YSU-GH-4C
- YSU-GH-6C
- YSU-GH-8C
- YSU-KM512i
- YSU-GH2220
- YSU-XG1024
- YSU-D-G5W
- YSU-D-G5UV
- YSU-D-G5UVCS
- YSU-S-G5UV
- YSU-C-G5UV
- YSU-C-CSG5UV
- YSU-S-KM1024i-13PL
- YSU-S-1024i
- YSU-S-1024i-UV
- YSU-5113
- YSU-EP4720
- YSU-C-KM13PLUV
- YSU-BYHX-1440UV-4C
- YSU-BYHX-1024i-13PL
- YSU_C_G5UV_CS600DPI
- YSU_C_CS_KM1024i13PL
- YSU_C_GH2220UV
- YSU_C_GH6090UV
- YSU_D_G5I
- YSU_D_G5I6090UV
- YSU-C-G6UVCS
- YSU-D-G5FZ
- YSU_D_G5I_4C
- YSU-C-G5
- YSU_D_G5I8C
- YSU_B_4C_G5UVCSJ
- YSU_2513UV
- YSU-D-1024I-1bit



- YSU-DPCS_G5I_600DPI
- YSU-B_I3200A1_CS
- YUEDA
- YD-BYHX-i3200
- YD-DPCS
- Yuxunda
- Yuxunda-HX
- Yuxunda-SY-XP600
- ZS
- ZS-AH480
- ZS-A520
- ZS-AD400
- ZXXD
- ZX2513-BYHX-G5
- ZX2513-BYHX-G6
- ZX2513-G5

New Cuter Drivers

- AM.CO.ZA
- V-Smart+ V3-1660-AML
- GCC
- JF-2418UG
- Kongsberg/Esko
- Kongsberg
- iCut
- LiYu Cut
- AutoMark-AML-HPGL
- Mimaki
- CJV330-130
- CJV330-160
- CG-60AR
- CG-100AR
- CG-130AR
- Roland



- TrueVIS VG3-300
- TrueVIS VG3-640
- TrueVIS VG3-540
- TrueVIS SG3-300
- TrueVIS SG3-640
- TrueVIS SG3-540
- VersaStudio BN-20A
- VersaUV LEC2-330 CMYKOrRWhWh
- VersaUV LEC2-640 CMYKOrRWhWh
- VersaUV LEC2-330 CMYKRePrGIW
- VersaUV LEC2-640 CMYKRePrGIW
- Saga
 - SAGA-490II
- Summa
 - GoProduce Laser
- Vinyl Express
 - Q30 Gen3
 - Q42 Gen3
 - Q54 Gen3
 - Q64 Gen3
- Vulcan
 - FC-500VC
 - FC-700VC
 - SC-350

Welcome to SAI Production Suite 21

The Flexi product group contains some of the world's most advanced tools for print production and sign making software. We have added many new features based on your feedback.

Operating Systems Supported

- Windows 11 64-bit (x64) processor



- Windows 10 32-bit (x86) or 64-bit (x64) processor
- Windows 8.1 32-bit (x86) or 64-bit (x64) processor

Installing on a Mac using parallels or bootcamp is not recommended and not supported.

SAi Production Suite 21 SP2

Build 3614

02 November 2021

Improvements

- Added tool to release variable data from the object
- Add a new type of mark, UV Curing Mark, for ImprimiPrinter
- New function for checking regions for RS license
- Reduce margin between the registration Marks and the Job for Zund Flatbed Cutter
- Image rotation can be saved with preset

Bug Fixes

- Updated PDF import to Mako 6.1.0
- Issue with test print and cut for OSC not working
- Issue with scaling when applying preset from the add job dialog
- Issue with Select Within causing program to close
- Fixed crash loading file with mask.
- Allow combining jobs that are with & without cut marks to a layer job
- Show a dialog with a link to download the B&D files when one of the tools for B&D is used and the Flexi3D files are missing
- Fix a crash in PDF parser that occurred in PDF files with 3-component ICCBased color spaces
- Fix generation of white data in RGB color mode
- Fixed handling BMP files with Asian characters in the path name
- Fixed crash while processing job with Contour cut line in sandwich mode



- Submitting too many jobs causes Caught Exception Error -6, fix a file handle leak with RipPNG filter
- Improve processing of PSD files
- Fix for label & dimension objects with missing fonts causing program to close
- Fixed crash caused by file with welded mask
- Fixed RIP error when using SAI Auto Mark
- Fixed an issue with gradients importing as solid colors
- Fix RIP error with ARMS New Plus mark for Titan cutter
- Issue with changing color of automatic label tool leaving extra stroke visible
- Fix issue opening SJP tab form Flexi Print SE and HP Basic
- Use different keys for 64-bit vs 32-bit Flexi preferences
- Issue with OPOS marks for nested jobs
- Fixed issue of some nested jobs not printing
- Exporting PDF with LAB colors
- Add import support for LAB-based colors with icc profiles
- Fixed rendering RGB+Spot for Canon GP printers
- Fix a bug that choking of spot channel data leaves some blank rows
- Fixed an issue with Error 216 when installing desktop driver
- Fixed issue of applying OCC when not using full color correction
- Fixed preview for cutmark line thickness
- Fixed issue with Graphtec reading marks when marks for each copy is applied
- Fixed "wrong data format" error with the Diptech Glassjet driver with floating point resolution
- Fixed output channel preview for variable data prints
- Fixed poll size for Mimaki JV100 on USB port
- Fixes for Mimaki UJV100 for FW 5
- Fixed Data Error for Epson SC-F10000
- Fixed misalignment of contour cut for Mimaki CJV 150
- Fix advance after plot issue for Mimaki cutters



- Fix a problem in rendering of images with transparency that have matching custom color mapping names and output spot channel name
- Fixed incorrect mirroring of the job in portrait orientation
- Fix a memory overrun loading an ICC with split tag of wrong size
- Fix a bug with Pantone colors rendering in RGB+W color mode
Canon GP printers
- Fixed font issues for Scandinavian characters
- Fixes for mask Printing
- Fix a bug that cut contour flag are not set in the paths inside compound objects after importing PDF files.
- Fix a crash removing shortcuts while uninstalling
- Fixed script error from Cloud Page
- Fix output of multiple pages in collate mode when there is a page range selection
- Fixed a shift in the job caused by incorrect job size when the job was mirrored and had grommets
- Fixed processing of transparent tiff

New Printer Drivers

- Canon: imagePROGRAF GP-4000, imagePROGRAF GP-540, imagePROGRAF GP-2000, imagePROGRAF GP-520, imagePROGRAF GP-300, imagePROGRAF GP-5300, imagePROGRAF GP-200, imagePROGRAF GP-5200
- HP: DesignJet Z6 Pro 64in, DesignJet Z9 Pro 64in
- Stratojet: Shark EFB-Series, Shark EFB-2512 ,Hawk EcoClean, Shark EFB-2032, Falcon XL-3300, Falcon XL -5300, Shark-III KM, Hawk, Shark-II, Piranha XT, Hawk CleanPrint, Falcon 1800B, Shark III-32R
-

New Cutter Drivers

- Graphtec: FCX4000-50, FCX4000-60,



SAi Production Suite 21 SP1

Build 3512

25 May 2021

Bug Fixes

- Barcode type grayed out for Graphtec marks
- Issue with non-ASCII characters in Variable Data Tool
- Creating layered jobs when setup is not active
- Standard OPOS marks not printing in German locale
- Several color issue for files with Lab colors
- Pure Hue settings are not being saved within presets
- Cutting on the Vinyl Express Q54 via USB port
- Send to RasterLink button not visible in Flexi 64-bit
- Poll size not working for Mimaki UCJV300 in 64 bit
- OPOS marks not showing for Summa S1 drivers
- Sending jobs to AM.CO.ZA FastCOLOUR-XP600 driver with port:
@AM_CO_ZA
- Add Setup failed for Canon imagePROGRAF iPF770
- Calculating offset in R&P
- Issues with some compound paths not opening correctly
- Cut and Print job not matching when cut job rotated
- Mimaki JXF not showing white channel in channel preview
- Drag and Drop images to VDT changes images order
- SinoColor console will not open Flexi 21 files
- Missing segmented marks for Graphtec FC 9000
- RIP error for tilled PSD files
- Epson files not installing correctly for Epson setup
- Trim mark cannot be applied to only one job in nested group



- Missing preview when sending file to desktop printer or when printing to PDF
- Select similar colors not working correctly
- Crash after undo on moving or rotating a character
- RIP error when file has gradient with thousands intermediate points
- Adding Titan cutter to the PM
- Barcode size issue for multi-page pdf
- Centering issue for Fujifilm Acuity LED 1600
- Patter film not transforming with the objects
- Issue with some gradients on object stroke
- Issue with undoing the transform of the object with gradient fill
- Issue with Sandwich mode when labels are used
- Labels for cutting parameters wrong in some languages

SAi Production Suite 21

Build 3484

23 March 2021

New Features

- Native 64-bit Flexi Design and Production Manager application
- Variable Data Printing
- JIG Template
- Layers Printing with multiple files
- Support for Illustrator layers in Production Manager for layers printing
- Output Channel Preview before RIP
- Artboard Contour Cut in Production Manager
- Enhanced Print while Rip for nested and tilled jobs
- User Data Backup
- Graphtec Barcode support
- Summa/HP OPOS Extra Mark Support
- Custom Outline Name and Colors
- Contour Cut Line Preview in Production Manager
- Device Link Profiler



- G7 Certification
- Custom Ink-set Support
- Adjust ICC by Color Mapping
- Output Size Compensation per Preset
- Contour Cut Jobs with Barcode to Stay in the Queue
- Manual Contour Cut Offset
- Improvement to Job Info
- Support for 64-bit Adobe Plugins

Bug Fixes from Flexi 19

- Update to the RIP engine has addressed several issues with ripping files including internal limit pdf interpreter to handle high resolution, issues with interpolated images, importing pdf files with multiple pages, rip errors when processing some JPG files
- Disabled Rotation for nested files that are bigger than media.
- Several issues with importing PDF and EPS files have been addressed with the update to importing filters, including files importing with missing elements, files importing with incorrect colors, files not importing into Flexi and files importing too slow.
- Addressed poll size subtracting margin value on HP Latex printers.
- Addressed Pantone V3 series color not displaying correctly in the gradient.
- Fixed incorrect ICC folder name for Roland TrueVIS VG2.
- Fixed issue with ripping PDF files with compressed objects while applying finishing bleed.
- Addressed issue with OPOS marks being placed on top of the graphics with certain gradients.
- Fixed issue with measurement line causing Flexi to close while saving file.
- Fixed issue of exporting eps files with 32 nit per pixel grayscale image.
- Improved precision of the preview for finishing tool.
- Fixed issue with color swatches not displaying correctly in Palette View.



- Addressed issue with shadow on PDF files from CorelDRAW.
- Addressed issue of copying certain vector images causing Flexi to become non-responsive.
- Addressed issues of keeping color space for individual object when exporting file as PDF.
- Addressed PDF box selection for jobs with finishing options.
- UI issue with color profilers when display scaling is not 100%.
- Issue importing SVG files.
- Issue with importing Adobe Illustrator files with large background images.
- Several issues with gradients when resizing, copying, and moving objects with the gradient fill.
- Applying Easy Weed line around groups of objects.
- Separation preview showing extra channels.
- Applying ContourCut with small negative offset on a circle object.
- Slow processing pdf files with embedded ICC profiles and Contour Cut line in Production Manager.
- Issue with gradients made from Pantone v3 color swatch.
- Addressed issue with layout changing in Production manger for print and cut jobs because of the offset.
- PDF import to preserve color space for ICC-based colors.
- Adding clearer message for corrupted/truncated preference file.
- PDF IA and Postscript files to respect cursor location when importing via drag-and-drop.
- Issue with tile map not being mirrored for tilled and mirrored jobs.
- Files send form Flexi Print DX Special Cloud Edition not importing with correct size into printer controller software.
- Addressed and issue with labels and marks not printing when media size is smaller than letter size.
- When applying file template in Designer file colors changed to black and white.
- Ripping issue for grayscale objects while Color Correction is off.
- Setting for automatic dimension saved as default.



- Spot Black mapping issue on Summa DC4.
- RIP issue when file has K channel mapped to Black and if Color Adjustment curve or contrast are changed.
- Issue with object under the lens effect being skipped during the export.
- Yellow channel not printing on Mutoh VJ1938TX.
- Drag Select preference not saved when selected in the preferences.
- Issue with Profiling Wizard getting channels info for custom ink-sets.
- Epson SC returns Error when selecting driver option in non-English language.
- Print wizard crashing in Chinese locale.
- Updated resolution modes for Mutoh PJ2508 UF.
- PNG size issue caused by rounding the resolution.
- Weed border not generated for Ioline Super 88\ 30 plotter
- Spot white not printing correctly as Fill when there are 2, 3 or 4 spot channels.
- Summa DC5sx feeds extra media after the end of the job.
- Printer Channel mapping issues.
- Multi Ink Limit issue in Wizard for Mutoh 1938 TX.
- Page Contour Mark not working for Foison.
- Calculating circumference of the circle for job statistics.
- Files printing Negative when Grayscale mode is selected.
- Gerber Edge marks not printing when All selected as Spot Color.
- Fuji Acuity printer not printing is color mode is set to 4C.
- LAB colors file printing incorrectly in Cannon Pro 4100s with no color correction.
- Wrong resolution causing incorrect scaling for desktop printers.
- Show Me option causing Off Scale error on the Graphtec plotter.
- Wrong Data error for large textile images on Epson 9470 and 9470 H.
- Orange not printing in CMYKlKlOr color mode on Galaxy UD-Ricoh Gen6.
- Lkk and Lk are not split and Lkk cannot be adjusted in Color Profiling Wizard.



- No white data when using custom spot color mapping on F-color printer.
- Adjust Similar Color in OCC not saved with preset.
- Wrong data error with Step and Repeat jobs of certain size and row option selected.
- Added option to break groups for True Shape Nesting.
- Straighten Pint tool causing crashing.
- PSD file preview and loading issues.
- Rasterizing adding extra pixels when margin is set to 0
- Issue with PDF ripping when file has 2 equal color names in DeviceN color space.
- Down sampling of bitmapped causing loss of measurement lines.
- Email and URL changed in Help and About window.
- Added applying of SILs separately, for both profiling targets and for color correction during RIP.
- Importing images with single-bit BlackWhite images

New Printer Drivers

- AC_ Color: AC-COLOR XG1024
- Agfa: Anapurna M254
- ALLWIN: ALLWIN-KS-I3200UV
- Ampla: New Elite, Elite, Elite FB, Cromax 1700S, Rio 8000s, Rio 8000, Targa, Targa XT 2013_14XT
- Avery Dennison: TrafficJet 1638X
- AW: AK-512i-30PL, MPADigital-1024A-UV6-28PL, AK-1024i-UV6PL-6C+W_RT, AK-EP3200-8C_RT
- Azon: Matrix Series 2 UV, Matrix Series 2 UV PRO, Matrix Series 2 UV DTS, Matrix Leather, Matrix Leather Pro, Matrix R 80DTS, Mirage, Hale
- BAITU: BAITU Dimatix SG1024
- BC Printer: ZT-WLY_6C, ZT-WLY_DX5, ZT-HS-3200, ZT-PH-4C, ZT-HS-4720, ZT-BY-TX800
- Bihong: BH-JetALL_Epson, BH-JetALL_SG, BH-Q_Jet_Kyocera



- Blueprint: Blueprint-Konica1024i-14pl, Blueprint-EX1600_EX1900, Blueprint-EPS-4720, Blueprint-EPSON-4720UV
- BLUEPRINT.ID: Model TX1802, Model TX1803, Model ES601, Model TX3200G, Model TX1800G
- Bossron: WT-SY-XP600, WT-SY-XP600-UV, WT-SY-XP600-6090UV, WT-BYHX-60HT, WT-BYHX-S60TH
- CaiYi: CaiYi_G5_R
- CALDRON: CG-SOL255-12PL4C, CG-SOL255-12PL6C, CG-SOL1020-35PL4C, CG-SOL1020-35PL6C, CG-SOL508GS4C, CG-SOL508GS6C, CG-SOL510-35PLD4C, CG-SOL510-35PL4C, CG-SOL510-35PL6C, CG-SOL510-50PL4C, CG-SOL510-50PL6C, CG-UV1020-4C, CG-UV1020-6C, CG-UV508GS4C, CG-UV508GS6C, CG-SOL1024GS-7pl, CG-RICHO5-UV, CG-TOCE4-UV, CG-EPSONII, CG-RICHO5-UV-WV, CG-EPSONI, CG-UV-1024GS-7pl, CG-UV-1024GS-7pl-MS, CG-Alpha1024, CG-RICOH6-UV, CG-KM512I, CG-EPSONIII, CG-ES-160
- Canon: imagePROGRAF TA-20, imagePROGRAF TA-5200, imagePROGRAF TA-30, imagePROGRAF TA-5300, imagePROGRAF TX-2100, imagePROGRAF TX-5210, imagePROGRAF TX-3100, imagePROGRAF TZ-5310, imagePROGRAF TZ-30000, imagePROGRAF TX-4100, imagePROGRAF TX-5410
- CK: AG9060UV, AG4560UV, AG100160UV
- Colorido: Colorido-4720
- CrystalJet: CJ-KM512I, CJ-EPSONIII, CJ-SG1024, CJ-KM1024I, CJ-KM1024A, CJ-KM512I-BYHX
- CSCAM: CSCAM_UV2020
- D-GEN: Teleios Grande G5, Teleios XL 2600, Artrix G5, Teleios Grande H6, Teleios HEXA, Arachne HEXA, Papyrus G5, Papyrus G5 H6, Artrix H8, Papyrus arete, Arachne arete, Teleios arete, Artrix arete' Papyrus Grande, Teleios Grande H12, Papyrus Grande G5
- Delone: Delone-EPSON-4720
- DGI: FT-1608, FT-1908, HS FT II, HS FT III, POSEIDON-1902, POSEIDON-1602, Hercules
- Digital Printer: TT-RY-GEN5, TT-4720-8C, TT-4720X-WV, TT-4720X-WV-Mini, TT-6C-2-WV-Mini, TT-HS4720-WV-Mini
- Dilli Precision: Neo Titan 1604-W2V, Neo Titan 1606, Neo Titan RTR 3204D-L
- DING: DING-SY-MinTX, DING-BYHX-MinTX, DING-AT-MinTX, DING-HX-MinTX, DING-HS-MinTX



- Diptech: LOGO Printer, GlassJet
- Edson: EDS-G5I, EDS-GH2220, EDS-GEN6, EDS-I3200
- EGERI: EGERI_XAAR_2001, EGERI_SY_DX5_7, EGERI_SY_DX5113_4720, EGERI_SY_XP600, EGERI_HS_4720
- Ejet: Ejet 609UV, Ejet_RICOH_GN6_BYHX
- Epson: SC-F9400, SC-F9460, SC-F9470, SC-F9440, SC-F9430, SC-F9480, SC-F9450, SC-F9400H, SC-F9460H, SC-F9470H, SC-F9440H, SC-F9430H, SC-F9480H, SC-F9450H, SC-F6300, SC-F6330, SC-F6340, SC-F6350, SC-F6360, SC-F6370, SC-F6380, SC-P9500, SC-P9530, SC-P9540, SC-P9550, SC-P9560, SC-P9570, SC-P9580, SC-P7500, SC-P7530, SC-P7540, SC-P7550, SC-P7560, SC-P7570, SC-P7580, SC-T3400, SC-T3430, SC-T3440, SC-T3450, SC-T3460, SC-T3470, SC-T3480, SC-T3405, SC-T3435, SC-T3445, SC-T3455, SC-T3465, SC-T3475, SC-T3485, SC-T5400, SC-T5430, SC-T5440, SC-T5450, SC-T5460, SC-T5470, SC-T5480, SC-T5400M, SC-T5430M, SC-T5440M, SC-T5450M, SC-T5460M, SC-T5470M, SC-T5480M, SC-T5405, SC-T5435, SC-T5445, SC-T5455, SC-T5465, SC-T5475, SC-T5485, SC-T5100, SC-T5130, SC-T5140, SC-T5150, SC-T5160, SC-T5170, SC-T5180, SC-T310, SC-T3130, SC-T3140, SC-T3150, SC-T3160, SC-T3170, SC-T3180, SC-T2100, SC-T2170, SC-T2150, SC-F1000, SC-F10030, SC-F10040, SC-F10050, SC-F10060, SC-F10070, SC-F10080, SC-F3000, SC-F3030, SC-F3050, SC-F3060, SC-F3070, SC-F3080, SC-R5000, SC-R5000L, SC-R5030, SC-R5030L, SC-R5040, SC-R5040L, SC-R5050, SC-R5050L, SC-R5070, SC-R5070L, SC-R5080, SC-R5080L, SC-V7000
- Eyecolor; Eyecolor-G5i-9060-JD, Eyecolor-KM512I-BYHX, Eyecolor-2513BY
- F-color: F-color_G5i_ATM, F-color_DZ_print mon, F-color_Ricoh_retch, F-color_KM_retch
- F-Print: F-PRINT_KM1024i_SHRY_UV, F-PRINT_KM512i_SHRY, F-PRINT_HS_S3200, F-PRINT_HS_S3200_UV, F-PRINT_DX5DX7_HS_UV
- FEDAR: FEDAR FD61815, FEDAR TC Series, FD Series
- Fei Yeung Union: EU-1000MF, FY- Series_XHS 1H4C, FY-BP Series_XHS 1H2C, FY-BP Series_FY 1H4C, FY-BP Series_FY 1H2C, FY-3200_Ricoh_RY, FY-I3200_HS, FY-CE4
- Flora: KM1024i-14pl, KM1024i-30pl, Flora-Gen5-720, Flora-PP2512UV-H, Flora-SPC-1800, Flora-SPC-2500, Flora-SPC-C25h, 3204P_15PL, 3204P_35PL, 3208P, 3202P, 3204P, Flora-XTRA5000SG, Flora-XTRA3200SG, Flora-LJ32-SG1024-360, Flora-LJ32-SG1024, XTRA320K512i, Flora-KM512i, Flora-TX-3200DS, Flora-LJ200T_KYC_4C



- Forni: Forni-Ricoh-BYHX, Forni-i3200UV-BYHX, Forni-Latex
- Fortune: YF-1800MH-CE4, YF-1800MH-G5, YF-1800MH-G6, YF-2512G6-HS, YF-1800MH-G6-HS, YF-1610-G5i, YF-2000-i3200, YF-2513-CE4, YF-2513G5i
- Fourstar: Fourstar-TS6070-G5
- GAIN: ARTJET-6090
- GCC: GCC JFT-2415UV, GCC JF-240UVII
- Gethray : Gethray-BYHX-KM1024I-30PL HI-UV, Gethray-UMC Gen6, Gethray-BYHX-GEN5, Gethray-BYHX-GEN6, Gethray-CR0701-DX5, Gethray-BYHX-I3200-UV, Gethray-BYHX-I3200
- GongZheng: GongZheng GZW2513_Gen, GongZheng GZT9060, GongZheng GZM3208KM, GongZheng GZW2513_Gen6, GongZheng GZT9060_i3200
- Great:GLT-3200G, GLT-2512G5, GLT-3300Z, GLT-1800ML, GLT-7590, GLT-KM2512K, GLT-2512G6, GLT-1610-CE4, GLT-1610-G5, GLT-1800MH-CE4, GLT-1800MH-G5, GLT-1800MH-G6, GLT-2512G6-HS, GLT-1800MH-G6-HS
- GZBK: GZBK-BJBK-JINDIE, GZBK-XP600-4C
- HandTop: HandTop HT2518UV-R, HandTop HT2500UV-R, HandTop HT2500UV-P, HandTop HT2512UV-P, HandTop HT3200UV-P, HandTop HT3200UV-R, HandTop HT3020UV-R, HandTop HT5000UV-K, HandTop HT3020UV-K, HandTop HT1610UV-R, HandTop HT1610UV, HandTop HT1610UV-T, HandTop HT3116UV-R, HandTop HT3116UV, HandTop HT3116UV-T, HandTop HT1600UV, HandTop HT1600UV-R, HandTop HT1600UV-T, HandTop HT2500UV-T, HandTop HT2512UV-T, HandTop HT3200UV-T, HandTop HT2512UV-R5, HandTop HT2500UV-R5, HandTop HT1600UV-R5, HandTop HT3116UV-R5, HandTop HT1610UV-R5, HandTop HT3200UV-R5, HandTop HT2512UV-X, HandTop HT3116UV-X, HandTop HT1600UV-X, HandTop HT2500UV-X, HandTop HT1610UV-X, HandTop HT3200UV-X, HandTop HT2512UV-K, HandTop HT3116UV-K, HandTop HT1600UV-K, HandTop HT2500UV-K, HandTop HT1610UV-K, HandTop HT3200UV-K, HandTop HT0604UV-R, HandTop HT0604UV-R5
- HCWY: HCWY-2512-S1600
- HP: HP Latex 700, HP Latex 700 W, HP Latex 800, HP Latex 800 W DesignJet Z6 Pro 64in, DesignJet Z9 Pro 64in, DesignJet Studio 36, DesignJet T650 36, DesignJet T630 36, DesignJet Studio 24, DesignJet T650 24, DesignJet T630 24, DesignJet T250 24, DesignJet T230 24, DesignJet T210 24
- HeXuan: HX-XP600, HX-8H Belt, HX-i3200, HX-i3200UV, M-COLOR-DX1100



- HKprinter: HKprinter-Water, HKprinter-UV
- HL: HL-X6-1806, HL-X6-2204, HL-I3200-UV, HL-I3200
- HongRun: HR-BYHX
- Honq: HY-7590, HY-KM2512, HY-KM2512K, HY-2512G6, HY-3202, HY-1810G5i, HY-2000D-BYHX, HY-1610-CE4, HY-1610-G5, HY-2000D-SY
- Honytek: Honytek-MU4720-360, Honytek-SY-4720, Honytek-BYHX-4720, Honytek-SY-I3200, Honytek-BYHX-I3200, Honytek-HS-4720-8C, Honytek-BYHX-4720-8C, Honytek-BYHX-I3200-9C
- Human Digital: HM H S3200 TX, HM B S3200 TX, HM B 4720 TX
- Icontek: TW-4720
- Impra, Impra-XP1601, Impra-XP1802, Impra-XP2502, Impra-XP3202, Impra-XP3204, Impra-DX1601, Impra-DX1802, Impra-DX2502, Impra-DX3202, Impra-DX3204
- ImprimiPrinter, ImprimiPrinter-ZB-DX5DX7, ImprimiPrinter-ZB-XP600, ImprimiPrinter-HS-XP600, ImprimiPrinter-HS-DX5DX7
- INNOVATION, IV_XP600, IV_3200
- JHF: JHF EPSON3200
- JiHui: JiHui-W, JiHui-O, JiHui-DX5DX7, JiHui-W5113, JiHui-DX5DX7-WV, JiHui-GEN5-4C-WV, JiHui-GEN5-6C-WV, JiHui-XP600-2HD, JiHui-AT-DX5DX7, JiHui-AT-5113, JiHui-HS-4720, JiHui-HS-4720-UV, JiHui-XP600-1HD, JiHui-HS-4720-Mini TX
- Jikji: Jikji_UV
- JSW: JSW XP600-JF, JSW SFast G5
- JUCAILI: JUCAILI-EP-HS, JUCAILI-EP-SY-DX5DX7-A, JUCAILI-EP-SY-DX5DX7, JUCAILI-EP-SY-5113, JUCAILI-EP-SY-XP600
- Kanishi: IJP-12C
- KingJet: SG1024-BYHX-8C, KingJet-SG1024-BYHX 16C, KingJet-XAAR-RY-4C, KingJet-XAAR-RY-6C, KingJet Scanning-RY-4C, KingJet-Scanning-RY-6C, KingJet-Scanning-RY-8C, KingJet-Scanning-RY-12C
- Kucai: KC-LT-4720-TX, KC-LT-4720-SY-TX, KC-LT-XP600-TX, KC-LT-4720-BJ-TX
- LETOP: LETOP-HS-DX5, LETOP-HS-DX5-UV, LETOP-HS-i3200, LETOP-HS-i3200-UV, LETOP-BJ-S1600-UV, LETOP-SY-XP600, LETOP-SY-i3200 LETOP-HS-XP600, LETOP-HS-XP600-UV, LETOP-BJ-512i, LETOP-UMC-512i, LETOP-HS-S1600-UV, LETOP-HS-G5-UV, LETOP-SY-DX5, LETOP-BJ-G5-UV, LETOP-HS-i3200-TX, LETOP-DPCS-G5I-UV



- LiYu: LY_KCP_KUA_4, LY_KCP_KUA_6, LY_DSJ_RA_PCIE, LY_DSJ_RA_BYHX, LY_FH_EB_4, LY_FH_EB_6, LY_KG253606_CR, LY_KCP_RA, LY_KCP_RB, LY_KC_RA_4, LY_KC_RA_6, LY_KCL_RA_4, LY_KCL_RA_6, LY_KCL_KY_4, LY_KCL_KY_6, LY_PCT_KU_4, LY_PCT_KU_6, LY_PN_KV_4, LY_PN_KV_6, LY_PN_KY_4, LY_PN_KY_6
- Locor: Locor-Ultra 1901
- Longier: LG-EP1902
- LongKe : LongKe-G6-6C, LongKe-S1600, LongKe-SG1024
- M-COLOR: M-COLOR-DX1100, M-COLOR-DX5700, M-COLOR-HW500
- MANPROTEK: MANPROTEK-I3200
- MAPD: MPAD Spirit A2
- MEGAJET: MEGA-EPXP600-HS-SUB, MEGA-EP4720-HS-SUB, MEGA-EPXP600-HS-ECO, MEGA-EP4720-HS-WV-PIGMENT
- Mehta RasterJet: RS-3200KMU 512i, RS-3200KMU 1024i, RS-2513G5U, RS-3200KMB 512i, RS-3200KMB 1024i, RS-3200SKY 1024HG
- MeiTu: MeiTu-GEN, MeiTu-GEN-B, MeiTu-GEN-C, MeiTu-DX-TX, MeiTu-GEN-4C-WV, MeiTu-GEN-6C-WV, MeiTu-1024i, MeiTu-Gen6-6C-WV
- Mimaki: UJV100-160, UCJV300-130 CMYKLcLmW, UCJV300-130 CMYK, UCJV300-107 CMYKLcLmW, UCJV300-107 CMYK, UCJV300-75 CMYKLcLmW, UCJV300-75 CMYK, JV300Plus-130, JV300Plus-160, SWJ-320EA, JV100-160, TS-100-1600
- Monotech: Pixel Jet Konica 3304L-KM1024-4C, Pixel Jet Konica 3304H-KM1024-4C, Pixel Jet KM512i JUMBO, Pixel Jet UV Flatbed F2512-R-GEN4-4C, Pixel Jet UV Flatbed F2512-R-GEN4-6C, Pixel Jet UV Flatbed F2512-R-GEN5-4C, Pixel Jet UV Flatbed F2512-R-GEN5-6C, Pixel Jet UV Flatbed F2512-R-GEN5-8C, Pixel Jet Eco Solvent 1800S, Pixel Jet Eco Solvent 1800TS, Pixel Jet SG1024 HS, Pixel Jet SG1024 HS1, Pixel Jet UV Mini Flatbed 1016
- MPADigital: MPAD-1024i-UV6PL, MPAD-1024A-UV6-28PL
- MT: MT-UV-0609PEII, MT-UV-0609XII-H, MT-UV0609II-2018, MT-UV6090III-MT
- Mutoh: XPJ-1682WR, VJ-628MP (KCMYLcLmLk)
- MyJet: Myjet JV33-160, MyJet-D_2_DX57YZ, MyJet-DX7_HS_UV, MyJet-DX5_HS_UV, MyJet-4720_HS, MyJet-G5_HS_4C_WV, MyJet-4720_SY, MyJet EP-MW, MyJet EP-MS, MyJet-HS_XP600_WCV, MyJet-HS_i3200_WCV
- MYMG PRINTER: MEGA-EPXP600-HS-SUB, MEGA-EP4720-HS-SUB, MEGA-EPXP600-HS-ECO, MEGA-EP4720-HS-WV-PIGMENT
- Nocai: Nocai-EP5113, Nocai-UV0609II-2018, Nocai-UV0609PEIII-MT, Nocai-UV0609ProII-H, Nocai-UV0609-CE4M-H



- Omajic: Omajic-UV2000, Omajic-UV_2513, Omajic-UV_3020, Omajic-HB_3200, Omajic-UV9060, Omajic-KM512I, Omajic-UV1016, Omajic-TX2PET, Omajic-1016, Omajic-HB_1800
- Online Digital: oneline-Toshiba-MINI UV, oneline-Toshiba-UV, oneline-MINI TX V2, oneline-8C
- OnePass: OnePass MorningStar-6C, OnePass MorningStar-8C
- OSNUO: OSN-7590, OSN-KM2512, OSN-KM2512K, OSN-2512G6, OSN-3202, OSN-1810G5i, OSN-2000D-BYHX, OSN-1610-CE4, OSN-1610-G5, OSN-2000D-SY, OSN-1800MH-CE4, OSN-1800MH-G5, OSN-1800MH-G6, OSN-2512G6-HS, OSN-1800MH-G6-HS
- Penghui: Penghui-UV
- Polar: PL-X6-2612, PL-Xaar-1201A-UV, PL-Xaar-1201B-UV, PL-KM-512I, PL-X6-6000G5-15C, PL-Xaar-MiniUV, PL-G5-MiniUV, PL-EPSON-MiniUV, PL-X6-1806, PL-X6-2204
- POLYTECH: POLYTECH-A, POLYTECH-B, POLYTECH-C
- PrintDot: PD-1809
- Printing, PRT-XP600, PRT-DX5DX7, PRT-4720, PRT-6090UV, PRT-5113, PRT-DX5DX7-A, PRT-XP600-UV
- PrismaJet, PrismaJet 1300_4C, PrismaJet 1600_4C, PrismaJet 1800_4C, PrismaJet 2600_4C, PrismaJet 3200_4C, PrismaJet 1800_6C_8C, PrismaJet 2600_6C_8C, PrismaJet DX 1601 S, PrismaJet 1800_6C_8C_VSD, PrismaJet 3200_4C_VSD, PrismaJet 1600_i3200, PrismaJet 1600-X, PrismaJet 3200-T, PrismaJet GZA_4C_8C, PrismaJet 3200_GZA, PrismaJet 1800_GZA, PrismaJet 1600-CF, PrismaJet DX 1602 S
- QSS GREEN: QSS GREEN 12C
- REVOTECH: REVOTECH-KHE-6PL-WV, REVOTECH-JF-KHE-Primer, REVOTECH-KHE-6PL-Primer, REVOTECH-KHE-6PL-Primer2, REVOTECH-JF-KHE-Primer2
- Ricoh: Ricoh Pro L5130e, Ricoh Pro L5160e, RICOH-Pro-TF6251-4C, RICOH-Pro-TF6251-5C, RICOH-Pro-TF6251-6C, RICOH-Pro-TF6251-7C
- Rikang: Rikang-YSY-426TX-B, Rikang-YSY-926-B, Rikang-YSY-426TX-H, Rikang-YSY-926-H
- Roland: TrueVIS VF2-640 TR2, TrueVIS VF2-640 TE2, VersaUV LEC2-300 CMYK, VersaUV LEC2-300 CMYKGIW, VersaUV LEC2-330 CMYK, VersaUV LEC2-640 CMYK, VersaUV LEC2-330 CMYKGIWhWh, VersaUV LEC2-640 CMYKGIWhWh, VersaUV LEC2-330 CMYKPrGIWhWh, VersaUV LEC2-640 CMYKPrGIWhWhRoland:



- Royal: Royal
- RoyalPrinter, RoyalJet UV1613 DX, RoyalJet UV1613 WDX
- SaiTu: SaiTu-JF-EP4720-8C, SaiTu-JF-EP4720, SaiTu-XAAR-2001, SaiTu-XAAR-2001-UV, SaiTu-JF-DX5-XP600, SaiTu-JF-DX5-XP600-UV, SaiTu-WLY-EP4720
- SAMPRINT: SAMPRINT SE series, SAMPRINT Se for oval, SAMPRINT Se-908 for wool, SAMPRINT Se-1502W_904W
- SD GROUP: SD-1800_4720_HS, SD-GD5000UV, SD-1800_G5i_DPCS, SD-3200_Ricoh_HSSD-1800_Ricoh_HS
- SENDOA: SENDOA-HECO1632DX, SENDOA-SECO1632DX
- ShenFa: ShenFa-EP4720
- ShinyColor: ShinyColor-I3200
- SID Signs: SID Triton Vista 180
- SignStar: SignStar-SFP-XP600UV
- SinoColor: SinoColor StormJet_9060, SinoColor DreamJet_9060, SinoColor ProJet_9060, SinoColor StormJet_DX, SinoColor DreamJet_DX, SinoColor ProJet_DX, SinoColor KMJet_DX, SinoColor UGJet_DX, SinoColor 0906i
- SMTJET: SMTJET-EP-DX5-HS, SMTJET-BYHX-DX5-8C
- Sprinter: Sprinter-RICOH-GEN5-CMY
- SUBLITECH: SUBLITECH_DX5DX7_150, SUBLITECH_DX5DX7_180, SUBLITECH_DX5DX7_HS_150, SUBLITECH_DX5DX7_HS, SUBLITECH_DX6_HS, SUBLITECH_W5113_HS, SUBLITECH_CE4, SUBLITECH_PC1080_HS_3S, SUBLITECH_HS_NET_EPS3200_V, SUBLITECH_HS_NET_EPS3200_LM, SUBLITECH_GN5_SHRY_ECO, SUBLITECH_HS_GN5_180, SUBLITECH_HS_GN5_150, SUBLITECH_HS_508GS, SUBLITECH_HYSH_512i, SUBLITECH_HS_KM1024i, SUBLITECH_HS_512i, SUBLITECH_DX5_BY
- SUNUSER: SUNUSER-E2513, SUNUSER-J2513
- Sunwin: JETWIN-XP, JETWIN UV-Gen5, JETWIN UV-EP3200. JETWIN 1024iUV, W-JET TX800-2513UV
- SUOJET, LJ320, LJ520, LJ6090-TOSHIBA, LJ6090-EPSON, LJ2513, LJ3220, LJ3625, LJ3200, LJ5200
- Taimex: Taimex-Xaar2001-WV, Taimex-TF9060A-CE4, Taimex-TF1016A-CE4, Taimex-TF9060-GEN5, Taimex-TF1016-GEN5, Taimex-TF9060-GH2220, Taimex-TF1016-GH2220, Taimex-EP4720-UV, Taimex-T2204G5i, Taimex-T1800UV-GEN5, Taimex-KM-1024i-13PL-UV, Taimex-GEN5-7PL-MC-4C



- TangHuaJi, THJ-HS-4720-Mini WX, THJ-W, THJ-O, THJ-DX5DX7, THJ-W5113, THJ-XP600-2HD, THJ-AT-DX5DX7 THJ-AT-5113, THJ-HS-4720, THJ-XP600-1HD
- TD Printer, TD-UV3050, TD-UV6040, TD-UV6090, TD-TX6040, TD-TX6090, TD-UV6090-XP600, TD-UV6090-DX7, TD-UV6090Pro, TD-TX6090-EPS
- Tecjet: TJet-MINI TX, TJet-CE4-MINI UV, TJet-CE4-UV, TJet-MINI TX V2, TJet-8C
- Textalk: Textalk TFR-6C, Textalk TFR912-2C-MINI, Textalk 4720-604, Textalk TFR912-2C-MINI-NEW, Textalk TFR-6C-Mini, Textalk TK-1804-Mini, Textalk TF-1804-2C-Mini, Textalk TR-1800, Textalk TR-3300, Textalk TE-1800, Textalk TE-2500, Textalk TR-1800-H, Textalk TR-3300-H, Textalk TE-1800-H, Textalk TE-2500-H
- ThunderJet: ThunderJet 3200_4C, ThunderJet 3200_4C_VSD, ThunderJet 1600_i3200, ThunderJet 1600-X, ThunderJet GZA_4C_8C, ThunderJet 3200_GZA, ThunderJet AWi3200, ThunderJet AC1800, ThunderJet 1800_4C_VSD, ThunderJet 3200_4C_VSD, ThunderJet AY1800
- Titan: TT-4720X-WV, TT-4720X-WV-Mini, TT-6C-2-WV-Mini, TT-HS4720-WV-Mini
- Twinjet: Twinjet SJ-1816Pro, Twinjet SJ-3200 4C, Twinjet TX-3200K-4C, Twinjet PHOENIX 3200-SM, Twinjet SJ-1605D, Twinjet BYHX-DX5-8C, Twinjet SJ-1832Pro, Twinjet ELASTEX 1832A, Twinjet PHOENIX 1832A, Twinjet PHOENIX 1832A-SM, Twinjet TX-1832A-4C, Twinjet TX-1832A-8C, Twinjet SJ-3232Pro, Twinjet PHOENIX 3232A, Twinjet PHOENIX 3232A-SM
- TXC TECH: TXC TECH-EP19, TXC TECH-EP20
- UVbetter: DX5789SmartUV, DX5789PlusUV
- WallPen: WallPen-2020
- Wit-Color Digital: ULTRA Starfire-BYHX, ULTRA UVIP_JD
- WuTe: WuTe-2513_UV, WuTe-XZJ_G5i, WuTe-PHJ_512i, WuTe-PBJ_DX7, WuTe-XZJ_4720, WuTe-2513_GH2220, WuTe-3020UV, WuTe-2513UV, WuTe-25001024i, WuTe-2513_MiniUV, WuTe-2513_GH2220MiniUV, WuTe-3020MiniUV, WuTe-G5iMiniUV
- X-Roland: X-Roland-HS-4720-Mini TX
- Xenons : Xenons-KM512I, Xenons-GJet2912-FR1024, Xenons RICOH-DX, Xenons-Vanish-Printer, Xenons-I3200, Xenons-I3200-UV
- XITU: XITU-HASON4720
- Xuli: XL-X6-1806, XL-X6-2204, XL-G6-HS, XL-Konica1024A-B, XL-I3200-UV, XL-I3200, XL-X6-3208
- XXPYFD: XXPYFD-BYHX, XXPYFD-ROYAL



- Y-PRINTER, YP-SY-XP600, YP-SY-DX5-A, YP-SY-DX5-B, YP-SY-DX5-Dual-A, YP-SY-DX5-Dual-B, YP-HS-EP
- YASELAN: YSL_D_G5I, YSL_D_G5I6090UV, YSL-C-G6UVCS, YSL-D-G5FZ, YSL_D_G5I_4C, YSL-C-G5, YSL_D_G5I8C, YSL_B_4C_G5UVCSJ, YSL_2513UV, YSL-D-1024I-1bit
- Yingcai: , YC2513-GEN5, YC2513-GH2220, YC2513-TX800, YC2513-DXF-S, YC2513-XP600-WLY, YC2513-GEN5-1H1C-HS, YC2513-GEN5-1H2C-HS, YC2513-1024GS, YC2513-KONICA-1024I, YC2513-GEN6-HS, YC2513-HS-4720, YC1313-XP600, YC1313-TX800, YC1313-DX5_7-HS, YC1313-GEN6-HS, YC1313-GEN5_RY, YC1313-GH2220, YC1016-XP600, YC1016-TX800, YC1016-DX5_7-HS, YC1016-GEN6-HS, YC1016-GEN5_RY, YC1016-GH2220, YC9060-XP600, YC9060-TX800, YC9060-DX5_7-HS, YC9060-GH2220, YC_A3_DXF_S, YC2513-DXF-S_WLY, YC-DX5789PlusUV
- YITE: YITE-BYHX-4720-UV
- Zind: UVjet 250
- ZXXD, ZX2513-RICOH-G5, ZX2513-RICOH-G6, ZX2513-KM1024I, ZX2513-HS-G5

New Cutter Drivers

- Aoke: Aoke-Cutter
- Duplo: DPC-2072, DPC-2054, DPC-2024
- GCC: Expert-24, GCC JF-240UV, RX II-61, Jaguar V-160, Jaguar V-61 LX, Jaguar V-160 LX, GCC JFT-2415UV, GCC JF-240UVII
- HP: Latex 64 Plus Cutter: Latex 54 Plus Cutter, Latex 54 Plus Basic
- IVANTEC: IVANTEC-Hibrido Co2
- Jingwei: LST-0604RM, LST03-0806RM
- Mehta Rex Digital Cutting Plotter: GRC-02, GRC-03, GRC-22, GRC-23, Ultra GRC-61, Ultra GRC-132S, Ultra GRC-76S, Ultra GRC-101S, Ultra GRC-30, Ultra GRC-50, Ultra GRC-60, UltraPlus GRC-50, Lynx S-60, Lynx S-30, Lynx S-132S, Jaguar JR-61, Jaguar JR-76S, Jaguar JR-101S, Jaguar JR-132S, Jaguar JII-61, Jaguar JII-76S, Jaguar JII-101S, Jaguar JII-132S, Jaguar III-61, Jaguar III-76, Jaguar III-101, Jaguar III-132, Jaguar III-183, Jaguar IV-61, Jaguar IV-76, Jaguar IV-101, Jaguar IV-132, Jaguar IV-183, Puma-60, Puma-30, Puma-132S, Puma II-60, Puma II-30, Puma II-132S, Puma III-60, Puma III-132S, Bobcat BI-30, Bobcat BI-60, Sable SB-60, Bengal BN-60, Expert-24, Expert-24 LX, Expert-52, Expert-52 LX, Puma IV-60, Puma IV-132, RX-61, RX-101, RX-132, RX-183, EnduraCut, Lynx III, Panther IV, GCC JF-



240UV, RX II-61, RX II-101, RX II-132, RX II-183, i-Craft, AR24, Expert II-24, Expert II-24 LX, Expert II-52, Expert II-52 LX, Jaguar V-61, Jaguar V-101, Jaguar V-132, Jaguar V-183, Jaguar V-160, Jaguar V-61 LX, Jaguar V-101 LX, Jaguar V-132 LX, Jaguar V-160 LX, Jaguar V-183 LX, Puma IV-60 LX, Puma IV-132 LX, Expert Pro-60, Expert Pro-132, RX II-61-CR, GCC JFT-2415UV, GCC JF-240UVII

- Mimaki: UCJV300-130 CMYKLcLmW, UCJV300-130 CMYK, UCJV300-107 CMYKLcLmW, UCJV300-107 CMYK, UCJV300-75 CMYKLcLmW, UCJV300-75 CMYK, CG-75FXII Plus, CG-130FXII Plus, CG-160FXII Plus
- MYCUT: MC630-AML, MC1200-AML
- Roland: TrueVIS SG2-640, TrueVIS SG2-540, TrueVIS SG2-300, TrueVIS VF2-640 TR2, TrueVIS VF2-640 TE2, VersaUV LEC2-300 CMYK, VersaUV LEC2-300 CMYKGIW, VersaUV LEC2-330 CMYK, VersaUV LEC2-640 CMYK, VersaUV LEC2-330 CMYKGIGIWhWh, VersaUV LEC2-640 CMYKGIGIWhWh, VersaUV LEC2-330 CMYKPrGIWhWh, VersaUV LEC2-640 CMYKPrGIWhWh
- Sky: C12-AML, C16-AML, C24-AML, V24-AML, V30-AML, V48-AML, V60-AML, D16-AML, D24-AML, D30-AML, D48-AML, D60-AML, A3 MAX-AML, F4560-AML, F6090-AML, F9012-AML
- Summa: S1 D60, S1 D75, S1 D120, S1 D140, S1 D160, S1 D140FX, D140FX, D160
- TPS: X3-AML, X5-AML, X7-AML, X8-AML, X9-AML
- Vinyl Express: M16, M24